







JWX-30

USER'S MANUAL

Roland DG Corporation

Thank you very much for purchasing this product.

- To ensure correct and safe usage with a full understanding of this product's performance, please be sure to read through this manual completely and store it in a safe location.
- O Unauthorized copying or transferral, in whole or in part, of this manual is prohibited.
- The contents of this operation manual and the specifications of this product are subject to change without notice.
- The operation manual and the product have been prepared and tested as much as possible. If you find any misprint or error, please inform us.
- O Roland DG Corp. assumes no responsibility for any direct or indirect loss or damage which may occur through use of this product, regardless of any failure to perform on the part of this product.
- Roland DG Corp. assumes no responsibility for any direct or indirect loss or damage which may occur
 with respect to any article made using this product.

For the USA

FEDERAL COMMUNICATIONS COMMISSION RADIO FREQUENCY INTERFERENCE STATE-MENT

NOTE:

This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the ECC Rules

These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment.

This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications.

Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

Unauthorized changes or modification to this system can void the users authority to operate this equipment.

Use only I/O cables that have been designed and manufactured specifically for this device.

For Canada

NOTICE

This Class A digital apparatus meets all requirements of the Canadian Interference-Causing Equipment Regulations.

AVIS

Cet appareil numérique de la classe A respecte toutes les exigences du Règlement sur le matériel brouilleur du Canada

NOTICE

Grounding Instructions

In the event of a malfunction or breakdown, grounding provides a path of least resistance for electric current to reduce the risk of electric shock. This tool is equipped with an electric cord having an equipment-grounding conductor and a grounding plug. The plug must be plugged into a matching outlet that is properly installed and grounded in accordance with all local codes and ordinances.

Do not modify the plug provided - if it will not fit the outlet, have the proper outlet installed by a qualified electrician.

Improper connection of the equipment-grounding conductor can result in a risk of electric shock. The conductor with insulation having an outer surface that is green with or without yellow stripes is the equipment-grounding conductor. If repair or replacement of the electric cord or plug is necessary, do not connect the equipment-grounding conductor to a live terminal.

Check with a qualified electrician or service personnel if the grounding instructions are not completely understood, or if in doubt as to whether the tool is properly grounded.

Use only 3-wire extension cords that have 3-prong grounding plugs and 3-pole receptacles that accept the tool's plug.

Repair or replace damaged or worn cord immediately.

— For California -

WARNING

This product contains chemicals known to cause cancer, birth defects and other reproductive harm.

Roland DG Corp. has licensed the MMP technology from the TPL Group.



Manufacturer:

ROLAND DG CORPORATION

1-6-4 Shinmiyakoda, Kita-ku, Hamamatsu-shi, Shizuoka-ken, 431-2103 JAPAN

The authorized representative in the EU:

Roland DG Corporation, German Office Halskestrasse 7, 47877 Willich, Germany

For EU Countries

WARNING

This is a Class A product. In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

Operating Instructions

KEEP GUARDS IN PLACE and in working order.

REMOVE ADJUSTING KEYS AND WRENCHES. Form habit of checking to see that keys and adjusting wrenches are removed from tool before turning it on.

KEEP WORK AREA CLEAN. Cluttered areas and benches invite accidents.

DON'T USE IN DANGEROUS ENVIRONMENT. Don't use power tools in damp or wet locations, or expose them to rain. Keep work area well lighted.

KEEP CHILDREN AWAY. All visitors should be kept safe distance from work area.

MAKE WORKSHOP KID PROOF with padlocks, master switches, or by removing starker keys.

DON'T FORCE TOOL. It will do the job better and safer at the rate for which it was designed.

USE RIGHT TOOL. Don't force tool or attachment to do a job for which it was not designed.

USE PROPER EXTENSION CORD. Make sure your extension cord is in good condition. When using an extension cord, be sure to use one heavy enough to carry the current your product will draw. An undersized cord will cause a drop in line voltage resulting in loss of power and overheating.

WEAR PROPER APPAREL. Do not wear loose clothing, gloves, neckties, rings, bracelets, or other jewelry which may get caught in moving parts. Nonslip footwear is recommended. Wear protective hair covering to contain long hair.

USE SAFETY GLASSES, face or dust mask if cutting or cleaning operation is dusty. Everyday eyeglasses only have impact resistant lenses, they are NOT safety glasses.

SECURE WORK. Use clamps or a vise to hold work when practical.

DON'T OVERREACH. Keep proper footing and balance at all times.

MAINTAIN TOOLS WITH CARE. Keep tools sharp and clean for best and safest performance. Follow instructions for lubricating and changing accessories.

DISCONNECT TOOLS before servicing; when changing accessories, such as blades, bits, cutters, and the like.

REDUCE THE RISK OF UNINTENTIONAL STARTING. Make sure switch is in off position before plugging in.

USE RECOMMENDED ACCESSORIES. Consult the owner's manual for recommended accessories. The use of improper accessories may cause risk of injury to persons.

NEVER STAND ON TOOL. Serious injury could occur if the tool is tipped or if the cutting tool is unintentionally contacted.

CHECK DAMAGED PARTS. Before further use of the tool, a guard or other part that is damaged should be carefully checked to determine that it will operate properly and perform its intended function - check for alignment of moving parts, binding of moving parts, breakage of parts, mounting, and any other conditions that may affect its operation. A guard or other part that is damaged should be properly repaired or replaced.

NEVER LEAVE TOOL RUNNING UNATTENDED. TURN POWER OFF. Don't leave tool until it comes to a complete stop.

USE POWER SUPPLY CORD WHICH IS ATTACHED WITH PRODUCTS. Do not use other power supply cord.

Contents

Content	s	3
⚠ To Er	nsure Safe Use	6
⚠ Pour	utiliser en toute sécurité	13
Importai	nt Notes on Handling and Use	20
	ne Documentation for This Machine	
, wout ti	Documentation Included with the Machine	
Chantar	1 Getting Started	
-	•	
1-1	Machine Highlights	
	What You Can Do with This Machine	
1-2	Part Names and Functions	
	Front and Interior	
	Side VPanel	
	Handy Panel and Built-in Panel	
0 1 4	,	
-	2 Installation and Setup	
	Checking the Included Items	
2-2	! Installation	
	About Emplacement and Installation	
	Installation Environment	
	Unpacking	
2.2	Installing the Dust Tray Cable Connections	
2-3	Connecting the Handy Panel	
	Connecting the Power Cord	
	Connecting to the Computer	
2-4	Installing and Setting Up the Software	
	System Requirements	
	The Software You Can Install and Set Up	37
	Installing the Windows-based Driver	38
	Installing and Setting Up VPanel	
2-5	Before Starting Operations	
	Spindle Run-in (Warm-up)	40
Chapter	3 Basic Operation	41
3-1	Starting and Quitting	42
	How to Start the Machine	
	How to Shut down	44
	Emergency Stop Due to Opening or Closing the Front Cover	45
3-2	Moving the Tool	46
	Manual Feed	46
	Viewing the Tool Location	
	Moving to a Specific Position	
0.0	Moving to the VIEW Position	
3-3	Starting and Stopping Spindle Rotation	
2 /	Starting or Stopping the Spindle	
3-4	Pausing and Quitting Cutting Pausing and Resuming Operation	
	Quitting CuttingQuitting Coperation	
3-5	Handy Panel	
0.0	Using the Handy Panel	

Chapter	4 Getting Ready for and Performing Cutting	55
4-1	Jig and Workpiece Selection	56
	Jig and Workpiece Selection	56
4-2	Installing a Tool	
	Installing a Tool	57
	Tool Selection	
4-3	Using the Square Clamp	59
	What You Can Accomplish Using the Square Clamp	59
	Square Clamp: Workpiece Size and Cuttable Area	60
	About the Milling Support Structure for Circumferential Cutting	
	Square Clamp: Attachment and Detection of Jig Location	
	Square Clamp: Two-surface Cutting	
	Square Clamp: Circumferential Cutting	
4-4	Using the Swivel Clamp	
	What You Can Accomplish Using the Swivel Clamp	
	Swivel Clamp: Part Names	
	Swivel Clamp: Workpiece Size and Cuttable Area	
	Swivel Clamp: Attachment and Detection of Jig Location	
	Swivel Clamp: Cutting While on the Rotary Axis	
	Swivel Clamp: Cutting While on the Table	
4-5	Using the Tube Clamp	
	What You Can Accomplish Using the Tube Clamp	
	Tube Clamp: Part Names	
	Tube Clamp: Workpiece Size and Cuttable Area	
	Tube Clamp: Attachment and Detection of Jig Location	
	Tube Clamp: Cutting	
4-6	Override	
	What's an Override?	
	How to Set Overrides	
4-7	Y- and Z-axis Origins: Concepts and Fine-tuning	
	Y- and Z-axis Origins: Concepts and Making the Settings	
	Fine-tuning the Y- and Z-axis Origin Points	
4.0	Determining the Adjustment Value	
4-8	Blower Fan	
	Using the Blower Fan	96
Chapter	5 Appendix	97
5-1	Maintenance	98
	Care and Maintenance of the Cutting Machine	98
	Care of the Detection Pin	
	Maintenance of the Spindle Unit	99
5-2	What to Do If	
	Initialization is not performed or initialization fails	
	VPanel doesn't start correctly	
	Operations are ignored	100
	The spindle doesn't rotate	
	Abnormal cutting is performed	101
	Jig detection failed	
	The feed rate or spindle speed is wrong	
	The cutting results are not attractive	
	Installation is impossible	
	Uninstalling the Driver	
	Responding to an Error Message	
	Power Rating and Serial Number Locations	
5-5	Expansion Connector Specification	
	Expansion Connector A	
	Expansion Connector B	108

5-6	Dimensional Drawings	109
	Dimension of Outline	
	Size of Each Jig	110
	X-, Y- and Z-axis Travel/ Table Dimension	
	Dimensional Drawings for Creating Milling Support Structure	114
5-7	Specifications	115
	Main Specifications	115
	System Requirements for USB Connection	

Company names and product names are trademarks or registered trademarks of their respective holders. Jewelry designs and photos in this manual courtesy Kristian Saarikorpi.


⚠ To Ensure Safe Use


Improper handling or operation of this machine may result in injury or damage to property. Points which must be observed to prevent such injury or damage are described as follows.


About A WARNING and A CAUTION Notices

⚠ WAF	RNING	Used for instructions intended to alert the user to the risk of death or severe injury should the unit be used improperly.		
⚠ CAUTION	Used for instructions intended to alert the user to the risk of injury or material damage should the unit be used improperly.			
	Note:	Material damage refers to damage or other adverse effects caused with respect to the home and all its furnishings, as well to domestic animals or pets.		

About the Symbols







! WARNING



Be sure to follow the operation procedures described in this documentation. Never allow anyone unfamiliar with the usage or handling of the machine to touch it.

Incorrect usage or handling may lead to an accident.



Keep children away from the machine.

The machine includes areas and components that pose a hazard to children and may result in injury, blindness, choking, or other serious accident.



Never operate the machine while tired or after ingesting alcohol or any medication. Operation requires unimpaired judgment. Impaired judgment may result in an accident.



Conduct operations in a clean, brightly lit location.

Working in a location that is dark or cluttered may lead to an accident, such as becoming caught in the machine as the result of an inadvertent stumble.



Never use the machine for any purpose for which it is not intended, or use the machine in an undue manner that exceeds its capacity.

Doing so may result in injury or fire.



Never use a cutting tool that has become dull. Perform frequent maintenance to keep and use the machine in good working order.

Unreasonable usage may result in fire or injury.



For accessories (optional and consumable items, power cord, and the like), use only genuine articles compatible with this machine.

Incompatible items may lead to an accident.

MARNING



Before attempting cleaning, maintenance, or attachment or detachment of optional items, disconnect the power cord.

Attempting such operations while the machine is connected to a power source may result in injury or electrical shock.



Never attempt to disassemble, repair, or modify the machine.

Doing so may result in fire, electrical shock, or injury. Entrust repairs to a trained service technician.

⚠ CAUTION



Never climb or lean on the machine.

The machine is not made to support a person. Climbing or leaning on the machine may dislodge components and cause a slip or fall, resulting in injury.

This machine weighs 47 kg (104 lb.)

A CAUTION



Unloading and emplacement are operations that must be performed by 2 persons or more.

Tasks that require undue effort when performed by a small number of persons may result in physical injury. Also, if dropped, such items may cause injury.

♠ CAUTION



Install in a location that is level and stable.

Installation in an unsuitable location may cause an accident, including a fall or tipover.

1 The cutting waste or workpiece may catch fire or pose a health hazard.

! WARNING



Never attempt to cut magnesium or any other such flammable material.

Fire may occur during cutting.



Keep open flame away from the work area.

Cutting waste may ignite. Powdered material is extremely flammable, and even metal material may catch fire.



When using a vacuum cleaner to take up cutting waste, exercise caution to prevent fire or dust explosion.

Taking up fine cuttings using an ordinary vacuum cleaner may cause danger of fire or explosion. Check with the manufacturer of the vacuum cleaner. When the safety of use cannot be determined, clean using a brush or the like, without using the vacuum cleaner.

A CAUTION



Wear dust goggles and a mask. Wash away any cutting waste remaining on the hands.

Accidentally swallowing or inhaling cutting waste may be hazardous to the health.

Danger of pinching, entanglement, and burns.

MARNING



Never attempt operation while wearing a necktie, necklace, loose clothing, or gloves. Bind long hair securely.

Such items may become caught in the machine, resulting in injury.



Securely fasten the cutting tool and workpiece in place. After securing in place, make sure no wrenches or other articles have inadvertently been left behind.

Otherwise such articles may be thrown from the machine with force, posing a risk of injury.



Exercise caution to avoid being pinched or becoming caught.

Inadvertent contact with certain areas may cause the hand or fingers to be pinched or become caught. Use care when performing operations.



Caution: cutting tool.

The cutting tool is sharp. To avoid injury, exercise caution.



Caution: high temperatures.

The cutting tool and spindle motor become hot. Exercise caution to avoid fire or burns.


Danger of electrical short, shock, electrocution, or fire

WARNING



Connect to an electrical outlet that complies with this machine's ratings (for voltage and frequency).

Provide a power supply whose amperage is 2.8 A or higher (for 100 to 120 V) or 1.2 A or higher (for 220 to 240 V).





Never use out of doors or in any location where exposure to water or high humidity may occur. Never touch with wet hands.

Doing so may result in fire or electrical shock.



Never allow any foreign object to get inside. Never expose to liquid spills.

Inserting objects such as coins or matches or allowing beverages to be spilled into the ventilation ports may result in fire or electrical shock. If anything gets inside, immediately disconnect the power cord and contact your authorized Roland DG Corp. dealer.



Never place any flammable object nearby. Never use a combustible aerosol spray nearby. Never use in any location where gases can accumulate.

Combustion or explosion may be a danger.

!∖ WARNING



Handle the power cord, plug, and electrical outlet correctly and with care. Never use any article that is damaged.

Using a damaged article may result in fire or electrical shock.



When using an extension cord or power strip, use one that adequately satisfies the machine's ratings (for voltage, frequency, and current).

Use of multiple electrical loads on a single electrical outlet or of a lengthy extension cord may cause fire.



When the machine will be out of use for a prolonged period, disconnect the power

This can prevent accidents in the event of current leakage or unintended startup.



Connect to ground.

This can prevent fire or electrical shock due to current leakage in the event of malfunction.



Position so that the power plug is within immediate reach at all times.

This is to enable quick disconnection of the power plug in the event of an emergency. Install the machine next to an electrical outlet. Also, provide enough empty space to allow immediate access to the electrical outlet.



Never use cutting oil.

This machine is not designed for the flow of cutting oil. Oil may get inside the machine and cause fire or electrical shock.



Never use a pneumatic blower.


This machine is not compatible with a pneumatic blower. Cutting waste may get inside the machine and cause fire or electrical shock.



If sparking, smoke, burning odor, unusual sound, or abnormal operation occurs, immediately unplug the power cord. Never use if any component is damaged.

Continuing to use the machine may result in fire, electrical shock, or injury. Contact your authorized Roland DG Corp. dealer.


⚠ Important notes about the power cord, plug, and electrical outlet




Never place any object on top or subject to damage.



Never allow to get wet.




Never bend or twist with undue force.




Never make hot.



Never pull with undue force.




Dust may cause fire.





Never bundle, bind, or roll up.

Warning labels are affixed to make areas of danger immediately clear. The meanings of these labels are as follows. Be sure to heed their warnings.

Also, never remove the labels or allow them to become obscured.










🖺 Pour utiliser en toute sécurité

La manipulation ou l'utilisation inadéquates de cet appareil peuvent causer des blessures ou des dommages matériels. Les précautions à prendre pour prévenir les blessures ou les dommages sont décrites ci-dessous.

Avis sur les avertissements

⚠ ATTENTION	Utilisé pour avertir l'utilisateur d'un risque de décès ou de blessure grave en cas de mauvaise utilisation de l'appareil.
↑ PRUDENCE	Utilisé pour avertir l'utilisateur d'un risque de blessure ou de dommage ma- tériel en cas de mauvaise utilisation de l'appareil.
Z. FRODENCE	* Par dommage matériel, il est entendu dommage ou tout autre effet indésirable sur la maison, tous les meubles et même les animaux domestiques.

À propos des symboles





⚠ L'utilisation incorrecte peut causer des blessures

ATTENTION



S'assurer de suivre les procédures d'utilisation décrites dans la documentation. Ne jamais permettre à quiconque ne connaît pas le fonctionnement ou la manutention de l'appareil de le toucher.

L'utilisation ou la manutention incorrectes peuvent causer un accident.



Garder les enfants loin de l'appareil.

L'appareil comporte des zones et des composants qui présentent un danger pour les enfants et qui pourraient causer des blessures, la cécité, la suffocation ou d'autres accidents graves.



Ne jamais faire fonctionner l'appareil après avoir consommé de l'alcool ou des médicaments, ou dans un état de fatigue.

L'utilisation de l'appareil exige un jugement sans faille. L'utilisation avec les facultés affaiblies pourrait entraîner un accident.



Utiliser l'appareil dans un endroit propre et bien éclairé.

Travailler dans un endroit sombre ou encombré peut causer un accident; l'utilisateur risque, par exemple, de trébucher malencontreusement et d'être coincé par une partie de l'appareil.



Ne jamais utiliser l'appareil à des fins autres que celles pour lesquelles il est conçu. Ne jamais l'utiliser de manière abusive ou d'une manière qui dépasse sa capacité.

Le non-respect de cette consigne peut causer des blessures ou un incendie.



Ne jamais utiliser un outil de coupe émoussé. Procéder fréquemment aux travaux d'entretien pour garder l'appareil en bon état de fonctionnement.

L'usage abusif peut causer un incendie ou des blessures.



Utiliser uniquement des accessoires d'origine (accessoires en option, articles consommables, câble d'alimentation et autres articles semblables), compatibles avec l'appareil.

Les articles incompatibles risquent de causer des accidents.

ATTENTION



Débrancher le câble d'alimentation avant de procéder au nettoyage ou à l'entretien de l'appareil, et avant d'y fixer ou d'en retirer des accessoires en option.

Tenter ces opérations pendant que l'appareil est branché à une source d'alimentation peut causer des blessures ou un choc électrique.



Ne jamais tenter de démonter, de réparer ou de modifier l'appareil.

Le non-respect de cette consigne risque de provoguer un incendie, un choc électrique ou des blessures. Confier les réparations à un technicien ayant la formation requise.

!∖ PRUDENCE



Ne jamais grimper ni s'appuyer sur la machine.

La machine n'est pas conçue pour supporter le poids d'une personne. Grimper ou s'appuyer sur la machine peut déplacer des éléments et causer un faux pas ou une chute, ce qui causerait des blessures.

⚠ PRUDENCE



Le déchargement et la mise en place doivent être faits par au moins 2 personnes.

Les tâches qui exigent un effort trop grand si elles sont exécutées par un petit nombre de personnes peuvent être cause de blessures. La chute d'articles très lourds peut aussi causer des blessures.

⚠ PRUDENCE



Installer l'appareil à un endroit stable et plat.

Installer l'appareil à un endroit inapproprié peut provoquer un accident grave comme le renversement ou la chute.

Les débris de coupe peuvent s'enflammer ou présenter un risque pour la santé.

ATTENTION



Ne jamais tenter de couper du magnésium ni aucun autre matériau inflammable.

Un incendie pourrait se produire pendant la coupe.



Ne pas approcher une flamme nue de l'espace de travail.

Les rognures de coupe peuvent s'enflammer. Les matériaux pulvérisés sont extrêmement inflammables et même le métal peut s'enflammer.



Si un aspirateur est utilisé pour ramasser les rognures de coupe, faire preuve de prudence pour empêcher que la poussière s'enflamme ou explose.

Ramasser des rognures fines à l'aide d'un aspirateur ordinaire peut créer un risque d'incendie ou d'explosion. Vérifier auprès du fabricant de l'aspirateur. Dans les cas où il est impossible de déterminer si un aspirateur peut être utilisé sans danger, se servir d'une brosse ou d'un article semblable plutôt que d'un aspirateur.

⚠ PRUDENCE



Porter des lunettes de protection et un masque. Rincer toutes les rognures de coupe qui pourraient rester collées aux mains.

Avaler ou respirer accidentellement des rognures de coupe peut être dangereux pour la



⚠ Certains éléments peuvent présenter un risque de pincement, d'emmêlement, de brûlure ou d'autres dangers.

!\ ATTENTION



Ne jamais faire fonctionner l'appareil si on porte une cravate, un collier ou des vêtements amples. Bien attacher les cheveux

Ces vêtements ou ces objets peuvent être coincés dans l'appareil, ce qui causerait des blessures.



Fixer solidement l'outil de coupe et la pièce à travailler. Une fois qu'ils sont fixés solidement, s'assurer qu'aucun outil ni aucun autre objet n'a été laissé en place.

Si tel était le cas, ces objets pourraient être projetés avec force hors de l'appareil et causer des blessures.



Faire preuve de prudence pour éviter l'écrasement ou le coincement.

La main ou les doigts peuvent être écrasés ou coincés s'ils entrent en contact avec certaines surfaces par inadvertance. Faire preuve de prudence pendant l'utilisation de l'appareil.



Attention: outil de coupe.

L'outil de coupe est acéré. Faire preuve de prudence pour éviter les blessures.



Attention : températures élevées.

L'outil de coupe et le moteur chauffent. Faire preuve de prudence pour éviter un incendie ou des brûlures.


Risque de décharge ou de choc électrique, d'électrocution ou d'incendie

ATTENTION



Brancher à une prise électrique conforme aux caractéristiques de cet appareil (tension et fréquence).

Il faut prévoir une alimentation en courant dont l'intensité est de 2.8 A ou plus (pour 100 à 120 V) ou de 1.2 A ou plus (pour 220 à 240 V).





Ne jamais utiliser à l'extérieur ni à un endroit où l'appareil risque d'être exposé à de l'eau ou à une humidité élevée. Ne jamais toucher l'appareil avec des mains mouillées.

Le non-respect de cette consigne risque de provoquer un incendie ou un choc élec-



Ne jamais insérer d'objet étranger dans l'appareil. Ne jamais exposer l'appareil aux déversements de liquides.

L'insertion d'objets comme des pièces de monnaie ou des allumettes, ou le déversement de liquides dans les orifices de ventilation peuvent causer un incendie ou un choc électrique. Si un objet ou du liquide s'infiltre dans l'appareil, débrancher immédiatement le câble d'alimentation et communiquer avec le représentant Roland DG autorisé.



Ne jamais placer d'objet inflammable à proximité de l'appareil. Ne jamais utiliser de produit inflammable en aérosol à proximité de l'appareil. Ne jamais utiliser l'appareil dans un endroit où des gaz peuvent s'accumuler.

Une combustion ou une explosion pourraient se produire.



Mise à la terre.

La mise à la terre peut prévenir un incendie ou un choc électrique dus à une fuite de courant en cas de défaillance.

ATTENTION



Manipuler le câble d'alimentation, la fiche et la prise électrique correctement et avec soin.

Ne jamais utiliser un article endommagé, car cela pourrait causer un incendie ou un choc électrique.



Si une rallonge ou une bande d'alimentation électrique sont utilisées, s'assurer qu'elles correspondent aux caractéristiques de l'appareil (tension, fréquence et courant). L'utilisation de plusieurs charges électriques sur une prise unique ou une longue rallonge peut causer un incendie.



Si l'appareil doit rester inutilisé pendant une longue période, débrancher le câble d'alimentation.

Cela peut prévenir les accidents en cas de fuite de courant ou de démarrage accidentel.



Placer l'appareil de façon à ce que la fiche soit facile d'accès en tout temps.

Ainsi, l'appareil pourra être débranché rapidement en cas d'urgence. Installer l'appareil près d'une prise électrique. En outre, prévoir suffisamment d'espace pour que la prise électrique soit facile d'accès.



Ne jamais utiliser d'huile de coupe.

Cet appareil n'est pas conçu pour traiter l'huile de coupe. L'huile peut s'infiltrer à l'intérieur et causer un incendie ou un choc électrique.



Ne jamais utiliser d'air sous pression.


Cet appareil n'est pas concu pour être nettoyé à l'aide d'un appareil soufflant. Des rognures de coupe peuvent s'infiltrer à l'intérieur et causer un incendie ou un choc électrique.



S'il se produit des étincelles, de la fumée, une odeur de brûlé, un bruit inhabituel ou un fonctionnement anormal, débrancher immédiatement le câble d'alimentation. Ne jamais utiliser si un composant est endommagé.

Continuer à utiliser l'appareil peut causer un incendie, un choc électrique ou des blessures. Communiquer avec le représentant Roland DG Autorisé.


Remarques importantes à propos du câble d'alimentation, de la fiche et de la prise électrique




Ne jamais déposer aucun objet sur le câble, sur la fiche ou sur la prise car cela risque de les endommager.



Ne jamais laisser l'eau toucher le câble, la fiche ou la prise.




Ne jamais plier ni tordre le câble avec une force excessive.




Ne jamais chauffer le câble, la fiche ou la prise.



Ne jamais tirer sur le câble ou la fiche avec une force excessive.



La poussière peut causer un incendie.





Ne jamais plier ni enrouler le câble.


⚠ Vignettes d'avertissement

Des vignettes d'avertissement sont apposées pour qu'il soit facile de repérer les zones dangereuses. La signification des vignettes est donnée ci-dessous. Respecter les avertissements.

Ne jamais retirer les vignettes et ne pas les laisser s'encrasser.







Important Notes on Handling and Use

This machine is a precision device. To ensure the full performance of this machine, be sure to observe the following important points. Failure to observe these may not only result in loss of performance, but may also cause malfunction or breakdown.

		-		
Ihie	machina	10 2	nracicion	MAVICA
11113	macmine	ıs a	precision	uevice.

- \bigcirc Handle carefully, and never subject the machine to impact or excessive force.
- Oliligently keep clean of cutting waste.
- Ouse within the range of specifications.
- O Never attempt to move the spindle head by hand with undue force.
- O Never needlessly touch anywhere inside the machine except for locations specified in this manual.

Install in a suitable location.

- O Install in a location that meets the specified conditions for temperature, relative humidity, and the like
- Install in a quiet, stable location offering good operating conditions.
- O Never install in out of doors.
- O Never use the machine in an environment where silicone substances (oil, grease, spray, etc.) are present. Doing so may cause poor switch contact.

This machine becomes hot.

- O Never cover the ventilation holes with cloth, tape, or anything else.
- O Install in a well-ventilated location.

This machine is exclusively for cutting modeling wax.

O Never cut any material other than modeling wax.

About Tools

○ The tip of the tool is breakable. Handle with care, being careful not to drop it.

About the Documentation for This Machine

Documentation Included with the Machine

The following documentation is included with the machine.

User's Manual (this manual)

This contains important notes for ensuring safe use, as well as detailed information on how to install and operate the machine and install and set up the included programs.

Be sure to read it first.

SRP Player Install Guide

This describes how to install and set up the included CAM programs, and how to view the online help that explains how to use the programs.

VPanel Online Help (electronic-format manual)

JewelStudio Online Help (electronic-format manual)


These are user's manual that you view on a computer screen, and they include detailed explanations of the commands used in the programs, as well as other information. Installing the respective programs makes these available for viewing.

P. 37, "Installing and Setting Up the Software"

How to View the Online Help


VPanel

From the [Start] menu(), click [All Programs], then [Roland VPanel for JWX-30]. Then click [Help].



JewelStudio

After starting JewelStudio, click then click [Help].



Chapter 1 Getting Started

1-1 Machine Highlights

What You Can Do with This Machine

A Machine Exclusively for Creating Jewelry Models

This machine is exclusively for making jewelry models. It is used to produce prototype models of jewelry using modeling wax. Installing and setting up the exclusive programs on your computer and connecting the machine to the computer enables you to create high-quality jewelry models in much less time than it would take to fashion them by hand.

Includes Special Jigs As Standard Features

The jigs needed to make a wide variety of jewelry, including rings, chaton settings, and brooches, are included with the machine as standard equipment. You select from among the three types of special jigs -- square clamps of two different sizes, a swivel clamp, and a tube clamp -- to match the task at hand, enabling you to create jewelry models of a rich range of designs.

Includes Special 3D CAD/CAM Programs As Standard Features

Versions of the JewelStudio 3D CAD program and the SRP Player 3D CAM program compatible with the machine's specifications are included as standard features. Using these programs lets you easily create the designs and tool paths for cutting that employ the included jigs.

Easy-operation VPanel and Handy Panel


VPanel, which you use once installed and set up on a computer, is the main operation panel for the machine, achieving ease of use with a large display area. Using VPanel, not only can you move the tool and switch the spindle on and off, you can also perform automatic detection of the location of the installed jig, make the settings for the origin points, and more. You can also operate the machine while watching the workpiece from close up by using the handy panel, which is capable of a subset of operations for tool movement and spindle on/off control.

Equipped with a High-performance Tool Sensor

The machine is equipped with the high-performance tool sensor needed to achieve high-precision cutting. Detection of the jig location and setting the reference position for cutting can be accomplished accurately thanks to this high-performance tool sensor, enabling you to create high-quality jewelry models.

1-2 Part Names and Functions

Front and Interior




P. 74, "Swivel Clamp: Attachment and Detection of Jig Location"


^{*}NOTE: In this manual, the mechanisms around the spindle unit, including the spindle motor, are called the "spindle head." Also, the rotary-axis area inside the spindle unit is called the "spindle."

Side

Left side




Right side



VPanel

Operation of the machine is controlled from the screen of your computer. VPanel is a dedicated program for controlling the machine.



① Coordinates

This displays the present tool location.

P. 47, "Viewing the Tool Location"

2 Feed buttons

These perform movement along the respective axes (X, Y, Z, and A).

P. 46, "Manual Feed"

③ Specific-destination movement button

You use this to make the tool move directly to a specific position.

P. 49, "Moving to a Specific Position"

④ Override buttons

These change the speed of spindle rotation and other aspects of cutting operations.

P. 93, "Override"

⑤ Base-point setting buttons

These set the base points used during cutting, such as the X- and Y-axis origin points.

6 Spindle speed

This displays the present rotating speed of the spindle. Changing the speed is also possible.

Spindle-rotation button

This switches spindle rotation on and off.

P. 50, "Starting and Stopping Spindle Rotation"

® Tool feed rate

This displays the present speed of tool movement.

This sets the reference position for the jig. Be sure to click this button whenever you've changed the jig.

10 Setup button

You use this at times such as when making settings to fine-tune the operation of the machine. For detailed information about the setting, refer to the online help of VPanel.

P. 21, "How to View the Online Help"


1 Preference button

You use this at times such as when setting the measurement unit used to display coordinates in VPanel. For detailed information about the setting, refer to the online help of VPanel.

¬ P. 21, "How to View the Online Help," p. 48, "Changing the Unit of Measurement for Display"

Handy Panel and Built-in Panel

You operate this machine using either the handy panel connected to the cutting machine by a cable, or the machine's built-in panel.



Status Indicated by the LEDs for the Built-in Panel

Name	LED state	Machine status
POWER	Lighted	The main power is on.
	Dark	The main power is off.
READY	Lighted	The sub power is on.
	Flashing	Initializing. The front cover is open. Tool movement is in progress. The spindle is rotating. Note: When in the four statuses described above, the machine accepts no cutting data that may be sent from the computer. Cutting is in progress. Cutting data is being processed.
	Dark	The sub power is off.
ERROR	Flashing slowly	A warning (nonfatal error) has occurred. (A description of the error is displayed in VPanel.)
	Flashing rapidly	An error resulting in an emergency stop has occurred. (A description of the error is displayed in VPanel.)
PAUSE (next to the PAUSE button)	Lighted	Operation is paused.

Chapter 2 Installation and Setup

2-1 Checking the Included Items

The following items are included with the machine. Make sure they are all present and accounted for.



Note*: This figure shows the state when shipped from the factory. For detailed information about the component parts, refer to page 72, "Swivel Clamp: Part Names," and page 84, "Tube Clamp: Part Names."

Note**: The Installation and Setup Guide for Roland JewelStudio is included with the Setup DVD-ROM.

2-2 Installation

About Emplacement and Installation

A WARNING

Unloading and emplacement are operations that must be performed by 4 persons

or more.

Tasks that require undue effort when performed by a small number of persons may result in physical injury. Also, if dropped, such items may cause injury.

The weight of the machine alone is 47 kg (104 lb.). Perform unloading and emplacement with care.

Installation Environment

Install in a quiet, stable location offering good operating conditions. An unsuitable location can cause accident, fire, faulty operation, or breakdown.

MARNING Install in a location that is level and stable.

Installation in an unsuitable location may cause an accident, including a fall or

tipover.

MARNING Never install in a location exposed to open flame.

Cutting waste may ignite. Powdered material is extremely flammable, and even

metal material may catch fire.

MARNING Never install close to any flammable object or in a gas-filled location.

Combustion or explosion may be a danger.

WARNING Never install outdoors or in any location where exposure to water or high humidity

may occur.

Doing so may result in fire or electrical shock.

MARNING Position so that the power plug is within immediate reach at all times.


This is to enable quick disconnection of the power plug in the event of an emergency. Install the machine next to an electrical outlet. Also, provide enough empty space

to allow immediate access to the electrical outlet.

- O Never locate in a location subject to wide fluctuations in temperature or humidity.
- O Never install in a location subject to shaking or vibration.
- O Never install in a location where the floor is tilted, not level, or unstable.
- O Never install in a dusty or dirty location, or outdoors.
- O Never install in a location exposed to direct sunlight or near air-conditioning or heating equipment.
- O Never install in a location exposed to considerable electrical or magnetic noise, or other forms of electromagnetic energy.
- O Never install in an environment where silicone substances (oil, grease, spray, etc.) are present.

Installation Space

Ensure that at least the following amount of space is available.



About the installation location

The height of installation should be 0.6 m (23.7 in.) or higher above the work floor.

This machine is desktop type. Install in a location that allows easy access to areas such as the main power switch during operation.

Unpacking


Retaining materials are attached to protect the machine from vibration during shipment. When installation is complete, remove these and store in the specified locations.

- O Remove all retaining materials. Any that remain may cause faulty operation or breakdown when the power is switched on
- O The retaining materials are required when moving the machine to a different location. Store them carefully so that they do not get misplaced.

A WARNING


Carry out these operations before you connect the power cord. Inadvertent powerup may result in pinched hands or other injury.

Removing the retainers



Make sure the power cord is not connected, then remove retainers A, B, and C.


Storing the retainers



You can attach retainers A and B at the location shown in the figure, and store the hexagonal wrench (used when replacing the spindle unit). Store retainer C so that it will not become misplaced, because it is also needed when relocating the machine.

Installing the Dust Tray

You use the dust tray with it placed between the rubber feet on the bottom of the machine.




2-3 Cable Connections

Connecting the Handy Panel

A CAUTION

Make sure the power to the machine is switched off before attempting to connect or disconnect the cables.

Connection or disconnection while the power is on may cause the machine to malfunction.



Connecting the Power Cord

⚠ WARNING Connect to an electrical outlet that complies with this machine's ratings (for volt-

age and frequency).

Provide a power supply whose amperage is 2.8 A or higher (for 100 to 120 V) or

1.2 A or higher (for 220 to 240 V).

MARNING Handle the power cord, plug, and electrical outlet correctly and with care. Never

use any article that is damaged.

Using a damaged article may result in fire or electrical shock.

⚠ WARNING When using an extension cord or power strip, use one that adequately satisfies

the machine's ratings (for voltage, frequency, and current).

Use of multiple electrical loads on a single electrical outlet or of a lengthy extension

cord may cause fire.

⚠ WARNING Connect to ground.

This can prevent fire or electrical shock due to current leakage in the event of


malfunction.

⚠ WARNING Connect to an electrical outlet. Never connect directly to a power distribution panel or other such fixed wiring equipment.

Doing so increases the hazard of fire or electrical shock.

This machine requires a single-phase commercial power supply.


○ 100 to 120 V: 2.8A or higher ○ 220 to 240 V: 1.2 A or higher



Connecting to the Computer

You use a USB cable to connect the machine and the computer. At this time, however, the connection to the computer must not be made yet. You make the connection to the computer when you install the Windows-based driver.

- P. 38 "Installing the Windows-based Driver"
- O Be sure to make the connection according to the instructions on page 38, "Installing the Windows-based Driver." Making the connection without doing so may cause driver installation to fail and make use impossible.
- O Never connect two or more machines of this model to a single computer.
- For the USB cable, use the included cable.
- O Never use a USB hub.



2-4 Installing and Setting Up the Software

System Requirements

Operating system	Windows 2000/XP/Vista/7 (32-bit or 64-bit versions) *Roland JewelStudio is not available for Windows 2000.
CPU	The minimum required CPU for the operating system
Memory	The minimum amount of required RAM for the operating system
Optical drive	CD-ROM drive
Video card and monitor	At least 256 colors with a resolution of 1,024 x 024 or mo re recommended)

This table shows the minimum system requirements for using VPanel for the JWX-30 and the Windows-based driver (JWX-30). For the system requirements for SRP Player and Roland JewelStudio, refer to the respective user's manuals. Installing JewelStudio requires a DVD-ROM drive.

For the latest information, see the Roland DG Corp. website (http://www.rolanddg.com).

The Software You Can Install and Set Up

VPanel for JWX-30	This is a dedicated program for controlling the modeling machine. You operate the modeling machine and make various settings using this program.
Windows driver (JWX-30 driver)	This is a Windows-based driver required for sending data from a computer to the machine.
SRP Player	This is a CAM program that imports general-use 3D data, such as IGES, DXF (3D), or STL, and outputs tool paths to the machine. Note: For information on installation and setup, refer to the separate SRP Player Installation and Setup Guide.
Roland JewelStudio	This is a 3D CAD program for designing jewelry models. It lets you create designs matched to the jigs included with the machine. Note: For more information on how to install and set it up, refer to the user's manual included with the Setup DVD-ROM.

Installing the Windows-based Driver



Notice

Keep machine and the computer unconnected until you carry out this installation operation. Failure to follow the correct procedure may make installation impossible.

Procedure

- Defore you start installation and setup, make sure the USB cable is NOT connected.
- 2 Log on to Windows as "Administrators."
- Insert the Roland Software Package CD-ROM into the computer. (Windows Vista only: When the automatic playback window appears, click [Run menu.exe].) The setup menu appears automatically.






Click [Install] of "Windows Driver".


An Installation and Setup Guide matched to the basic software on your computer is displayed. If you're using Windows 2000, the Installation and Setup Guide and the "Driver Setup" appear.





Follow the instructions in the Installation and Setup Guide to finish installing.

After installation is completed, the window for the setup menu appears again. Go on to "Installing and Setting Up VPanel" on the following page.



Installing and Setting Up VPanel

Procedure


1 Display the window for the setup menu.





Click [Install] of "VPanel for JWX-30."





When the screen shown in the figure appears, click [Next], then follow the prompts to install and set up the program. (Windows Vista only: The [User Account Con-

trol] appears, click [Allow].)

When installation finishes, the screen shown at left appears. Click [Finish].

Click of the install window.

This completes the installation.

2-5 Before Starting Operations

Spindle Run-in (Warm-up)

In any of the following cases, perform run-in (warm-up) operation for the spindle. Failure to do so may result in unstable spindle rotation.

- O When using for the first time after purchase
- O After moving the machine and reinstalling it at a different location
- O After replacing the spindle unit
- \bigcirc When using in a low-temperature environment

How to Perform Run-in (Warm-up) Operation

Carry out the following steps 1 through 3.

P. 50, "Starting and Stopping Spindle Rotation"

Step1

Speed: 6,000 rpm

Rotation time: 20 minutes

Step2

Speed: 15,000 rpm

Rotation time: 20 minutes

Step3

Speed: 30,000 rpm Rotation time: 20 minutes

Chapter 3 Basic Operation


3-1 Starting and Quitting

How to Start the Machine

Follow the procedure below to start the machine. When startup is complete, the machine is ready for use.


Procedure






Close the front covers.





Switch on the main power. The POWER light comes on.






Switch on the sub power.

The spindle head moves to the back left of the machine, and the table moves to the back. The READY light flashes at this time. This operation is called initialization. When the READY light stops flashing and remains steadily lighted, initialization is complete.






On the computer, start VPanel. From the [Start] menu, click [All Programs] -[Roland VPanel for JWX-30] - [VPanel].

The window shown in the figure appears. Startup of the machine is complete.


How to Shut down

Procedure





On the computer, quit VPanel. Click [Close].



Switch off the main power.
The POWER light and READY light go dark.


Emergency Stop Due to Opening or Closing the Front Cover

To ensure safety, opening a front cover during cutting or spindle rotation causes an emergency stop to occur. The ERROR light on the cutting machine flashes and VPanel displays the message shown below. Operation cannot be resumed by closing the front cover. To resume, follow the on-screen instructions to restart.

P. 42, "Starting and Quitting"



Clicking [OK] at this window makes the window disappear, but the window reappears until the cutting machine's power is switched off.



3-2 Moving the Tool

Manual Feed

Moving the tool manually is called "manual feed," and you can accomplish this using the feed buttons in VPanel.




Table Movement When a Y-axis Feed Button Is Clicked

Under the default setting, Y-axis movement assumes a direction of tool movement relative to the object being cut. This means that clicking a Y-axis feed button makes the table move in a direction different from what the arrow indicates.

Note: Manual feed cannot be performed while a cutting operation is in progress.

Operation Using the Handy Panel


You can also perform this operation using the handy panel.

P. 54, "Using the Handy Panel"

Viewing the Tool Location

Coordinate View

VPanel displays the present location of the tool as numerical values. The numerical values that indicate the location of the tool are called "coordinates," and the starting point for the coordinates is called the "origin point," or sometimes just the "origin." The following figure shows a location that is shifted from the origin point by 30 millimeters along the X axis, by 10 millimeters along the Y axis, by 20 millimeters along the Z axis, and by 45 degrees along the A axis. This X-axis distance is called the "X-axis coordinate" (or sometimes just the "X coordinate"), the Y- and Z-axis distances are similarly called the "Y-axis coordinate" and the "Z-axis coordinate," and the angle of rotation along the A axis is called the "A-axis coordinate." The distances or the angle from the origin point for the respective axes to the tool are therefore the corresponding coordinate values.



About the A-axis Coordinate


The location of the A axis is indicated as an angle of rotation. In this way it differs from how the X, Y, and Z axes are indicated. Despite this difference between angles and distances, in other respects it is treated the same as X-, Y-, and Z-axis coordinates. The unit of measurement used to indicate A-axis coordinates is the degree, and this cannot be changed.

Selection of the Coordinate System

On this machine, you can switch the display between the following two coordinate systems.


- O User Coordinate System: This is a coordinate system in which the location of the origin point can be freely changed.
- O Machine Coordinate System: This is a machine-specific coordinate system in which the location of the origin point is fixed and cannot be changed.

For the operations on this machine, it may be a good idea to leave the selection at "User coordinate system" at all times. When you want to know the absolute location of the tool on this machine, select the machine coordinate system.




Changing the Unit of Measurement for Display

You can switch the unit of measurement used for displaying coordinates between millimeters and inches. Click the [Preference], then select the unit.



Moving to a Specific Position



Selecting a destination from the list and clicking the [Move] button makes the tool move rapidly to the selected location. Clicking the [Stop] button stops movement.


Note: Movement to "ZCL Y Origin" is possible only when detection of the jig location has been performed and the center of the axis of rotation has been established.

© P. 62, "Square Clamp: Attachment and Detection of Jig Location," p. 74, "Swivel Clamp: Attachment and Detection of Jig Location," p. 86, "Tube Clamp: Attachment and Detection of Jig Location"

When "User Specify" Is Selected

Clicking the [Move] button makes the window shown at left appear. You can specify the location of the movement destination by entering the values you want for "Coordinates" or "Amount of relative movement."

Moving to the VIEW Position




Press the VIEW button on the built-in panel.

The tool moves to the highest position, after which the tool moves to the center of the machine and the table moves to the front of the machine. This location is called the "VIEW position." You use this when performing such operations as attaching or detaching a tool, installing a jig, or mounting a workpiece. The READY light flashes while movement is in progress. When the READY light stops flashing and remains steadily lighted, movement is complete.

This operation cannot be performed while a front cover is open. Close the front cover, then perform the operation.

3-3 Starting and Stopping Spindle Rotation

Starting or Stopping the Spindle



Close the front covers and click

In the spindle begins to rotate.
Clicking a second time stops the spindle rotation.

Setting the Spindle Speed During Cutting

The spindle's rotating speed during cutting operations is controlled by commands in the cutting data sent from the computer, and so the setting made in VPanel is ignored. Note, however, that the setting made with VPanel is used when the cutting data contains no command specifying the spindle speed, or if the setting is made again in VPanel while cutting is in progress. You can also use VPanel's override feature to adjust the speed of spindle rotation during cutting.

P. 93, "Override"

Operation Using the Handy Panel

You can start and stop spindle rotation using the handy panel. Changing the speed of rotation using the handy panel is not possible.


P. 54, "Using the Handy Panel"

3-4 Pausing and Quitting Cutting

Pausing and Resuming Operation


This operation pauses cutting. You perform it using the built-in panel. This also makes it possible to resume cutting at the paused position after an operation such as moving the tool to check the status of the workpiece.

Procedure



Press the PAUSE button during cutting.


Tool movement pauses. The PAUSE light comes on and the READY light flashes. Rotation of the spindle does not stop at this time.



Press the VIEW button.

Rotation of the spindle stops, the tool moves to the center of the machine, and the table moves to the front of the machine (the VIEW position). The READY light flashes while the tool and table are moving.

This operation cannot be performed while a front cover is open. Close the front cover, then perform the operation.



Hold down the PAUSE button for one second or longer.

The tool returns to the position where operation was paused, and cutting resumes. After the tool starts moving, the PAUSE light flashes until cutting resumes. After cutting resumes, the PAUSE light goes dark.

This operation cannot be performed while a front cover is open. Close the front cover, then perform the operation.

Important!

Before opening the front cover while operation is paused, first make sure that rotation of the spindle is stopped. For safety, opening the front cover while the spindle is turning makes the machine perform an emergency stop. Be sure to note that if this happens, it's necessary to quit the operation and start over from the beginning.

P. 45 "Emergency Stop Due to Opening or Closing the Front Cover"

Other Operations Possible While Paused

VPanel

- \bigcirc Tool movement using manual feed
- P. 46, "Manual Feed"
- \bigcirc Starting or stopping spindle rotation
- P. 50, "Starting and Stopping Spindle Rotation"
- OChanging the spindle speed
- P. 93, "Override"
- O Adjusting the tool feed rate

Handy Panel


- OStarting or stopping spindle rotation
- P. 54, "Using the Handy Panel"
- Moving the tool
- P. 54, "Using the Handy Panel"

Quitting Cutting

This stops cutting through operation using the built-in panel. Unlike pausing operation, cutting cannot be resumed.

Procedure






Press the PAUSE button during cutting.

Movement of the tool pauses. The PAUSE light comes on and the READY light flashes. Rotation of the spindle does not stop at this time.






Hold down the CANCEL button for two seconds or longer.

When the POWER light goes dark and the READY light is lighted, cutting has completed stopping. Rotation of the spindle stops at this time.

3-5 Handy Panel

Using the Handy Panel

This is an operation panel connected to the cutting machine by a cable. You can use it to perform such operations as moving the tool or switching spindle rotation on and off. This makes it a handy tool when you want to perform operations while monitoring the material or the tool position from a location close to the machine.





X-, Y-, and Z-axis movement buttons

These are the respective movement buttons for the X, Y, and Z axes. Pressing just these buttons performs slow movement.

Y-axis movement assumes a direction of tool movement relative to the object being cut. This means that pressing v or makes the table move in the direction opposite to what the arrow indicates v :movement toward the back of the machine, :movement toward the front of the machine).



A-axis button

Pressing this button makes the movement axis change to the A axis. Pressing this button does not actually rotate the A axis. To rotate the A axis, you press this button, then turn the dial.



Feed button

Pressing a movement button or turning the dial while holding down this button performs rapid movement.



Spindle button

Holding this down for one second or longer while the spindle is stopped sounds an audible beep and starts spindle rotation. Pressing this during spindle rotation sounds a beep and stops rotation.



LEDs

This indicates the axis of movement using the handy panel. Pressing the movement button for an axis makes the corresponding LED light up.



Dial

Turning this moves the selected axis (the axis whose LED is illuminated).

Operating the Handy Panel and VPanel at the Same Time


Never operate the handy panel and VPanel simultaneously. Operation using VPanel becomes impossible while the handy panel is being used.

Chapter 4 Getting Ready for and Performing Cutting

4-1 Jig and Workpiece Selection

Jig and Workpiece Selection

Select the jig and workpiece to match the design and size of the jewelry model you want to produce. The cutting method varies according to the type of the jig. Select a jig and workpiece shape that match the purpose of what you're creating.



NOTE*: This machine is exclusively for working modeling wax. Never cut any material other than modeling wax.

4-2 Installing a Tool

Installing a Tool

This describes how to install a tool for cutting. You can use the same method to install a detection pin.

MARNING Never inadvertently touch the computer or handy panel while performing this

task.

Unintended operation of the machine may result in injury.

⚠ WARNING Securely fasten the cutting tool and workpiece in place. After securing in place, make sure no wrenches or other articles have inadvertently been left behind.

Otherwise such articles may be thrown from the machine with force, posing a risk

of injury.

CAUTION Caution: cutting tool.


The cutting tool is sharp. To avoid injury, exercise caution.

Procedure

Close the front covers and move to the VIEW position. When movement to the VIEW position is complete, open the front covers.

P. 49, "Moving to the VIEW Position"






Loosely tighten the collet.

Secure the spindle unit in place using the 17-mm spanner, then screw in the collet until it is finger-tight.





Insert the tool into the collet until it makes flush contact.


The collet included with the machine is magnetic at the location where the tool makes contact. Attaching a tool included with the machine at that location results in an amount of extension of the tool tip of approximately 30 millimeters.

Even when you're using a collet or tool other than one that came with the machine, it's still a good idea to adjust the amount of extension of the tool tip to around 30 millimeters. Also, use a collet and tool of matching diameters.

For a detection pin

Be sure to use with the tool flush against the magnetic area of the collet. Otherwise, detection of the jig location may fail.





Fully tighten the collet.

Using two spanners, tighten the collet fully. The appropriate tightening torque is 3.2 N-m (32 kgf-cm).

Tool Selection

Select a tool matched to the purpose. It's a good idea to use the tools selectively, according to the work process (such as rough cutting or finish cutting) and the design.

Features of the Included Tools

Ball end mill (CAP-LN-BED)

This has a cutting blade around the outer-perimeter surface of the tool tip, and the end cutting edge is ball-shaped. The end face of the cutting path is formed in a curve in the shape of the end cutting edge, so this tool is not suitable when you want to create angles. It may be a good idea to use it mainly for rough cutting of outer shapes and the like.

Conical end mill (ZEC-J3015)

The tool tip is tapered, making this suitable for finely detailed cutting. It may be a good idea to use this mainly for finishing intricate areas.

Detection pin

You use this when performing detection of the jig location. It is not used in actual cutting. The presence of rust or grime can make accurate detection impossible, so keep it clean through daily care.

P. 99, "Care of the Detection Pin"

Important Notes When Using Tools Not Included with the Unit

When you're using a tool other than one that's included with the machine, give careful attention to such matters as the length of the tool and the shape of its tip. When deciding on the tool length and amount of extension, take into account the machine's operating stroke in the height direction and the size of its cutting area. In particular, an amount of extension that is too large may cause the tool to strike the jig or the table and break. A tool that has an extremely narrow tip may also break when it touches the tool sensor, and so such tools should be used with caution.

P. 60, "Square Clamp: Workpiece Size and Cuttable Area," p. 72, "Swivel Clamp: Workpiece Size and Cuttable Area," p. 85, "Tube Clamp: Workpiece Size and Cuttable Area," p. 113, "X-, Y- and Z-axis Travel/Table Dimension"

4-3 Using the Square Clamp


What You Can Accomplish Using the Square Clamp

Using the square clamp, you can carry out what's called "two-surface cutting" and "circumferential cutting." You can carry out two-surface cutting followed by circumferential cutting to produce a jewelry model for a ring, or perform just two-surface cutting to create a brooch-type jewelry model. Circumferential cutting requires first fashioning a milling support structure for securing the workpiece in place on the square clamp, and so performing only circumferential cutting alone is not possible. Select the size of the square clamp to match the size of the jewelry model you want to produce.

Two-surface Cutting

This method performs cutting with the workpiece held immobile by the frame portion of the square clamp. This makes it possible to cut the surfaces one at a time by rotating the workpiece by 180 degrees. When you're following this with circumferential cutting, you create a milling support structure in this cutting process.


P. 61, "About the Milling Support Structure for Circumferential Cutting"



Circumferential Cutting

This method performs cutting with the workpiece held immobile at the tip of the square clamp. This involves holding the workpiece immobile at an orientation different from two-surface cutting, making it possible to cut areas that the blade cannot reach in two-surface cutting. Securing the workpiece in place requires a milling support structure, and so this milling support structure must be fashioned using two-surface cutting.


P. 61, "About the Milling Support Structure for Circumferential Cutting"




Square Clamp: Workpiece Size and Cuttable Area

The size of the workpiece that can be mounted in the jig and the actual cuttable area are different. The cuttable area is also the cutting area that can be set with SRP Player, the CAM program included with the machine. Refer to the figure below to determine the size of the workpiece to use and the size of the jewelry model you're producing.

Two-surface Cutting




Circumferential Cutting



About the Milling Support Structure for Circumferential Cutting

Circumferential cutting using the square clamp requires a milling support structure for holding the workpiece immobile at the tip of the square clamp. You fashion the milling support structure using two-surface cutting so as to fit the shape of the tip of the square clamp. The JewelStudio program that comes with the machine includes cutting data for creating a milling support structure, so create the cutting data as described in the user's manual for JewelStudio. If you're using a 3D CAD program other than JewelStudio, create the cutting data with reference to page 114, "Dimensional Drawings for Creating Milling Support Structure."

P. 21, "How to View the Online Help," p.114, "Dimensional Drawings for Creating Milling Support Structure"



Square Clamp: Attachment and Detection of Jig Location

⚠ WARNING Never inadvertently touch the computer or handy panel while performing this

Unintended operation of the machine may result in injury.

⚠ WARNING Securely fasten the jig in place. After securing in place, make sure no wrenches or other articles have inadvertently been left behind.

Otherwise such articles may be thrown from the machine with force, posing a risk of injury.


Attach the square clamp and carry out detection of the jig's location. The method you use to attach the square clamp is always the same, regardless of the size of the square clamp.

Important!

- O Detecting the location of the jig is a necessary procedure for determining the reference position for cutting. Be sure to carry this out whenever you change the jig.
- O Attach correctly. If it is not attached properly, detection of the jig location cannot be carried out correctly.
- O Make sure the square clamp, detection pin, and tool sensor are clean and free of any buildup of cutting waste or the like. Any buildup on these may prevent correct response by the sensor and make correct detection of the jig location impossible. In some cases, such buildup may cause breakage of the detection pin, resulting in injury or damage.


Procedure

- Olose the front covers and perform movement to the VIEW position.
- P. 49, "Moving to the VIEW Position"
- 2 Open the front covers and install the detection pin.
- P. 57, "Installing a Tool"
- Mount the square clamp on the rotary axis.




4 Secure the square clamp in place with the clamp holder.

Fit the rail on the clamp holder into the groove in the table, slide the clamp holder to fit it onto the tip of the square clamp, then tighten the cap screw on the clamp holder to secure the holder in place. If the tip of the square clamp does not easily fit into the clamp holder, temporarily loosen the cap screws at the junction of the square clamp and the rotary axis, then secure the clamp holder in place. Then secure the square clamp in place again on the rotary axis.








Close the front covers, then in VPanel, click [Change Jig].
The [Jig Detection] window appears.






Select "SQUARE CLAMP [L]" (or "SQUARE CLAMP [S]").

A picture of the selected jig appears. If you're using the square clamp, "L" is displayed for the large clamp, or "S" for the small one.

Important!

- OSelect the correct jig. Detection may fail if the wrong jig is selected. In some cases, the machine may be damaged.
- O Remove the screw at the tip of the square clamp. Detection may fail if it is not removed. In some cases, the detection pin may break.





Click [Start Sensing].

Detection of the location of the jig starts.

When the window shown in the figure appears, click [OK].

Click [Close].

When detection of the location of the jig is finished, set the base point, then proceed with carrying out actual cutting.

P. 65, "Square Clamp: Two-surface Cutting"


Square Clamp: Two-surface Cutting

Before Starting Cutting

- O Make sure that detection of the jig location has finished. If detection of the jig location has not finished, the intended cutting may not be possible.
- P. 62, "Square Clamp: Attachment and Detection of Jig Location"

Procedure





Perform movement to the VIEW position and open the front covers.

Mount the workpiece in the square clamp.


Secure in place using the sub-clamp. Secure firmly enough to keep the workpiece from coming loose easily.

P. 49, "Moving to the VIEW Position"

2 Install a cutting tool.

P. 57, "Installing a Tool"

3



Close the front covers and make the setting for the base point. Select "XYZ origin at frame center," then click [Apply].


The origin point for the X, Y, and Z axes is set at the center of the square clamp's frame.

Make sure no buildup of cutting waste is present on the tool sensor, then click [Continue].

The tool moves and descends to the position where it touches the tool sensor. During detection, the window shown in the figure is displayed.

Click [OK].

The X-, Y-, and Z-axis origin point has been set.



5 Send cutting data from the computer and start cutting.

P. 61, "About the Milling Support Structure for Circumferential Cutting"



Point

When the tool type has been changed during cutting, the base point must be set again to match the new tool. In such cases, go back to step ③, redo the setting, then resume cutting.

6 When cutting has finished, perform movement to the VIEW position. Open the front covers and remove the workpiece.

This completes the two-surface cutting. If the sub-clamp is toward the back of the machine, then to make the workpiece easier to remove, use VPanel to move the rotary axis to "A Origin." After detaching the workpiece, trim away any excess areas.

P. 49, "Moving to a Specific Position," "Moving to the VIEW Position"
If you're continuing with performing circumferential cutting, then go on to the following page.


Square Clamp: Circumferential Cutting

Before Starting Cutting

- O Make sure that detection of the jig location has finished. If detection of the jig location has not finished, the intended cutting may not be possible.
- P. 62, "Square Clamp: Attachment and Detection of Jig Location"
- O Performing circumferential cutting using the square clamp requires a milling support structure for mounting the workpiece at the tip of the square clamp. You can create a milling support structure by means of two-surface cutting.
- F. 61, "About the Milling Support Structure for Circumferential Cutting," p. 65, "Square Clamp: Two-surface Cutting"

Procedure





Attach the workpiece at the tip of the square clamp, securing it in place with the screw.

Orient the milling support structure so that its flat cutting surface is placed against the tip of the square clamp. Attaching it in the reverse orientation makes it impossible to update the cutting data correctly.


Tighten the screw enough to keep the workpiece from coming loose easily.

2 Install a cutting tool.

P. 57, "Installing a Tool"



4




Close the front covers and make the setting for the base point. Select "XYZ origin at tip," then click [Apply].

The origin point for the X, Y, and Z axes is set at the tip of the square clamp.

Make sure no buildup of cutting waste is present on the tool sensor, then click [Continue].

The tool moves and descends to the position where it touches the tool sensor. During detection, the window shown in the figure is displayed.



Click [OK].

The X, Y, and Z origin point has been set.

5 Send cutting data from the computer and start cutting.



Point

When the tool type has been changed during cutting, the base point must be set again to match the new tool. In such cases, go back to step ③, redo the setting, then resume cutting.

6 When cutting has finished, perform movement to the VIEW position. Open the front covers and remove the workpiece.

After detaching the workpiece, trim away any excess areas.

P. 49, "Moving to a Specific Position," "Moving to the VIEW Position"


4-4 Using the Swivel Clamp

What You Can Accomplish Using the Swivel Clamp

You can use the swivel clamp with it mounted either on the rotary axis or on the table. You can produce jewelry models for chaton settings and other such pieces that require multiple-surface cutting by performing cutting on the rotary axis, then changing to the table. You can also perform cutting on just the rotary axis or just the table.


Cutting using the rotary axis

This method performs cutting with the swivel clamp on which the workpiece is mounted secured to the rotary axis. It lets you perform multiple-surface cutting while rotating the workpiece.




Cutting on the table

This method performs cutting with the swivel clamp on which the workpiece is mounted secured to the table. This performs cutting only from above the workpiece, with no movement of the workpiece during cutting.




Swivel Clamp: Part Names




Swivel Clamp: Workpiece Size and Cuttable Area

The size of the workpiece that can be mounted in the jig and the actual cuttable area are different. The cuttable area is also the cutting area that can be set with SRP Player, the CAM program included with the machine. Refer to the figure below to determine the size of the workpiece to use and the size of the jewelry model you're producing.

Cutting While on the Rotary Axis



Cutting While on the Table



Swivel Clamp: Attachment and Detection of Jig Location

⚠ WARNING Never inadvertently touch the computer or handy panel while performing this

Unintended operation of the machine may result in injury.

⚠ WARNING Securely fasten the jig in place. After securing in place, make sure no wrenches or other articles have inadvertently been left behind.

Otherwise such articles may be thrown from the machine with force, posing a risk

of injury.

Attach the swivel clamp and carry out detection of the jig's location. Even when you're carrying out cutting on only the rotary-axis side or only the table side, detection of the jig location is performed at both places. Performing detection at only one side is not possible.

Important!

- O Detecting the location of the jig is a necessary procedure for determining the reference position for cutting. Be sure to carry this out whenever you change the jig.
- O Attach correctly. If it is not attached properly, detection of the jig location cannot be carried out correctly.
- O During detection of the jig's location, keep the retaining rings (both A and B) detached from the clamp base. Detection of the jig location cannot be performed correctly when the retaining rings remain attached.
- O Make sure the swivel clamp, detection pin, and tool sensor are clean and free of any buildup of cutting waste or the like. Any buildup on these may prevent correct response by the sensor and make correct detection of the jig location impossible. In some cases, such buildup may cause breakage of the detection pin, resulting in injury or damage.

Procedure


• Close the front covers and perform movement to the VIEW position.


P. 49, "Moving to the VIEW Position"

2 Open the front covers and install the detection pin.

P. 57, "Installing a Tool"


3 Mount the square clamp on the rotary axis.





Close the front covers, then in VPanel, click [Change Jig]. The [Jig Detection] window appears.






Select [Swivel Clamp].
A picture of the selected jig appears.

Important!

- Select the correct jig. Detection may fail if the wrong jig is selected. In some cases, the machine may be damaged.
- O Remove the retaining rings (both A and B). Correct detection is impossible when the retaining rings are left attached.






Click [Start Sensing].


Detection of the location of the jig starts.





When the screen shown in the figure appears, open the front covers, detach only the swivel clamp's clamp base from the rotary axis, then attach it to the adapter on the table.





Close the front covers and click [OK]."

Detection of the location of the jig starts.

When the window shown in the figure appears, click [OK].

Click [Close].

When detection of the location of the jig is finished, set the base point, then proceed with carrying out actual cutting.

P. 78, "Swivel Clamp: Cutting While on the Rotary Axis," p. 81, "Swivel Clamp: Cutting While on the Table"


Swivel Clamp: Cutting While on the Rotary Axis

Before Starting Cutting

- O Make sure that detection of the jig location has finished. If detection of the jig location has not finished, the intended cutting may not be possible.
- P. 74, "Swivel Clamp: Attachment and Detection of Jig Location"
- O This section describes how to perform cutting on the rotary axis, followed, when necessary, by cutting on the table. For cutting on the table first (or for cutting only on the table), refer to page 81, "Swivel Clamp: Cutting While on the Table."

Procedure






Perform movement to the VIEW position and open the front covers

Detach the clamp base.

P. 49, "Moving to the VIEW Position"






Attach the retaining rings (A and B) to the clamp base.


Here, tighten retaining ring A loosely (about two turns).

3



Mount the workpiece.

Insert the workpiece, then tighten the retaining ring A.




Mount the clamp base with workpiece on the rotary axis adapter.

6 Install a cutting tool.

P. 57, "Installing a Tool"






Close the front covers and make the setting for the base point. Select "XYZ origin at rotary-axis clamp," then click [Apply].

Make sure no buildup of cutting waste is present on the tool sensor, then click [Continue].

The tool moves and descends to the position where it touches the tool sensor. During detection, the window shown in the figure is displayed.





Click [OK].

The X, Y, and Z origin point has been set.


Send cutting data from the computer and start cutting.



Point

When the tool type has been changed during cutting, the base point must be set again to match the new tool. In such cases, go back to step ③, redo the setting, then resume cutting.





When cutting has finished, perform movement to the VIEW position.

Open the front covers, and without detaching the workpiece from the clamp base, remove the clamp base from the adapter.

This completes cutting on the rotary axis. If you're continuing with cutting performed on the table, proceed to the following page.


Swivel Clamp: Cutting While on the Table

Before Starting Cutting

- O Make sure that detection of the jig location has finished. If detection of the jig location has not finished, the intended cutting may not be possible.
- P. 74, "Swivel Clamp: Attachment and Detection of Jig Location"
- This section describes how to perform cutting on the rotary axis, followed immediately by cutting on the table. For cutting on the table first (or for cutting only on the table), mount the workpiece using the method described on page 78, "Swivel Clamp: Cutting While on the Rotary Axis," steps ① through ③.


Procedure





Leaving the workpiece you've cut on the rotary axis attached to the clamp base, attach the clamp base to the adapter on the table. (For cutting on the table first [or for cutting only on the table], mount the workpiece using the method described on page 78, "Swivel Clamp: Cutting While on the Rotary Axis," steps through).) When you're continuing with cutting on the rotary axis, detaching the workpiece causes the reference position to be misaligned and makes it impossible to perform the intended cutting.

2




Close the front covers and make the setting for the base point. Select "XYZ origin at table clamp," then click [Apply].

Make sure no buildup of cutting waste is present on the tool sensor, then click [Continue].

The tool moves and descends to the position where it touches the tool sensor. During detection, the window shown in the figure is displayed.

3



Click [OK].

The X, Y, and Z origin point has been set.

Send cutting data from the computer and start cutting.



Point

When the tool type has been changed during cutting, the base point must be set again to match the new tool. In such cases, go back to step ②, redo the setting, then resume cutting.

When cutting has finished, perform movement to the VIEW position.

Open the front covers, and without detaching the workpiece from the clamp base, remove the clamp base from the adapter.


This completes cutting on the table. When you're following this immediately with cutting on the rotary axis, detach the clamp base while keeping the cut workpiece attached to it, then go on to page 78, "Swivel Clamp: Cutting While on the Rotary Axis," step ."

P. 78, "Swivel Clamp: Cutting While on the Rotary Axis," step ...


4-5 Using the Tube Clamp

What You Can Accomplish Using the Tube Clamp

Using tube clamp, you can carry out cutting while rotating the cylindrical workpiece. This enables you to create batches of ring-shaped jewelry models efficiently.




Tube Clamp: Part Names



Tube Clamp: Workpiece Size and Cuttable Area

The size of the workpiece that can be mounted in the jig and the actual cuttable area are different. The cuttable area is also the cutting area that can be set with SRP Player, the CAM program included with the machine. Refer to the figure below to determine the size of the workpiece to use and the size of the jewelry model you're producing.



Tube Clamp: Attachment and Detection of Jig Location

⚠ WARNING Never inadvertently touch the computer or handy panel while performing this

task.

Unintended operation of the machine may result in injury.

⚠ WARNING Securely fasten the jig in place. After securing in place, make sure no wrenches

or other articles have inadvertently been left behind.

Otherwise such articles may be thrown from the machine with force, posing a risk

of injury.

Attach the tube clamp and carry out detection of the jig's location.

Important!

- O Detecting the location of the jig is a necessary procedure for determining the reference position for cutting. Be sure to carry this out whenever you change the jig.
- O Attach correctly. If it is not attached properly, detection of the jig location cannot be carried out correctly.
- O Make sure the tube clamp, detection pin, and tool sensor are clean and free of any buildup of cutting waste or the like. Any buildup on these may prevent correct response by the sensor and make correct detection of the jig location impossible. In some cases, such buildup may cause breakage of the detection pin, resulting in injury or damage.

Procedure


Olose the front covers and perform movement to the VIEW position.

P. 49, "Moving to the VIEW Position"

2 Open the front covers and install the detection pin.


P. 57, "Installing a Tool"


3 Mount the tube clamp.




Secure the tube clamp in place using the clamp holder.

Fit the rail on the clamp holder into the groove in the table, slide the clamp holder to fit it onto the tip of the tube clamp, then tighten the cap screw on the clamp holder to secure the holder in place. If the tip of the tube clamp does not easily fit into the clamp holder, temporarily loosen the cap screw at the junction of the adapter and the shaft, then secure the clamp holder in place. Then secure the junction for the adapter and the shaft in place again.





Close the front covers, then in VPanel, click [Change Jig].
The [Jig Detection] window appears.




Select [Tube Clamp]. A picture of the selected jig appears.

Important!

O Select the correct jig. Detection may fail if the wrong jig is selected. In some cases, the machine may be damaged.





Click [Start Sensing]. Detection of the location of the jig starts.

When the window shown in the figure appears, click [OK].

Click [Close].

When detection of the location of the jig is finished, set the base point, then proceed with carrying out actual cutting.


Tube Clamp: Cutting

Before Starting Cutting

- O Make sure that detection of the jig location has finished. If detection of the jig location has not finished, the intended cutting may not be possible.
- P. 86, "Tube Clamp: Attachment and Detection of Jig Location"

Procedure






Perform movement to the VIEW position and open the front covers.

Detach the clamp holder and shaft.

P. 49, "Moving to the VIEW Position"






Mount the workpiece.

Mounting the workpiece requires applying force to press it in. For this reason, mounting the workpiece while leaving the shaft attached to the adapter may apply excessive force to the jig or the rotary axis, which may result in a problem. When you're mounting the workpiece, be sure to first detach the shaft from the adapter.






Attach the shaft with the workpiece mounted on it to the adapter, and secure the tip of the shaft in place using the clamp holder.

Install a cutting tool.

P. 57, "Installing a Tool"



6



Close the front covers and make the setting for the base point. Select "YZ origin at center of rotation," then click [Apply].


The origin point for the Y and Z axes is set at the center of the rotary axis (the center of the A axis).

Make sure no buildup of cutting waste is present on the tool sensor, then click [Continue].


The tool moves and descends to the position where it touches the tool sensor. During detection, the window shown in the figure is displayed.

Click [OK].

The Y- and Z-axis origin point is set at the center of rotation of the A axis.







Set the X-axis origin point. Move the tool to the place you want to make the X-axis cuttingstart location, select the [Set "X Origin" here] check box, then click

The X-axis coordinate value changes to "0.00 mm." This completes the settings for the base point.

P. 46, "Manual Feed"

[Apply].


Send cutting data from the computer and start cutting.



Notice

When the tool type has been changed during cutting, the base point must be set again to match the new tool. In such cases, go back to step 5, redo the setting, then resume cutting.

9



When cutting has finished, detach the workpiece.


Detach the clamp holder, then rotate the wheel on the shaft in the direction shown in the figure to push the sleeve out. When the turning of the wheel stops, remove the workpiece.

4-6 Override

What's an Override?

On this machine, you can adjust the cutting speed and the speed of spindle rotation while cutting is in progress. You adjust these by specifying the ratio of change relative to the present speed, as a percentage. This feature is called "override." This feature is useful when you want to change the respective speeds on the fly as you monitor the status of cutting.

How to Set Overrides



Cutting-speed Override

This is the speed of tool movement when cutting the workpiece. The speed specified by the command in the cutting data is taken to be 100%.

Spindle Override

This is the speed of spindle rotation. The speed specified by the command in the cutting data is taken to be 100%. This is also effective when rotating the spindle during manual operations.

Important Notes on Overrides

Setting an override does not let you perform operation beyond the machine's maximum or minimum speeds.

4-7 Y- and Z-axis Origins: Concepts and Fine-tuning

Y- and Z-axis Origins: Concepts and Making the Settings


On this machine, cutting is performed using a rotary axis, and so the thinking behind setting the origin points is different from three-axis cutting that uses only the X, Y, and Z axes. This is because rotating the A axis changes the positional relationship between the workpiece and the origin points, making it impossible to know the reference position for cutting. In such cases, it is most common to set the Y- and Z-axis origin points at the center of the A axis.

On this machine, during detection of the jig location, the center of the A axis is detected. The machine is also designed to set the respective origin points for the X, Y, and Z axes at the detected center of the A axis. This means that you can set the Y- and Z-axis origin points at the center of the A axis by following the setting methods using jigs that are described in chapter 4 of this manual.

Fine-tuning the Y- and Z-axis Origin Points

When you want to adjust the position of the A-axis center obtained through jig-location detection more exactly, refer to the method described below.


Procedure




Move the tool to the Y origin point.

In VPanel, select "Y origin" and click [Move].

P. 49, "Moving to a Specific Position"



Move the Y axis the distance of the adjustment value.



Make the setting for the base point.

Select "Y-origin" and click [Set].

The method just described is for fine-tuning the Y-axis origin point. Use the same method for the Z-axis origin point as well


For information on how to determine the adjustment value, refer to the following section.

Determining the Adjustment Value

Adjustment Value for the Y-axis Origin

You determine the adjustment value from the difference in levels at the seam produced between the first and second surfaces in two-surface cutting. The estimated adjustment value is one-half the difference in levels. However, be careful to note the sign of the value (plus or minus). As the figure shows, the sign of the adjustment value (positive or negative) changes depending on the direction of the misalignment.

As an example, when the difference in levels is 0.2 millimeters, with the upper level misaligned in the positive direction and the lower level misaligned in the negative direction along the Y axis, then the estimated adjustment value is -0.1 millimeters.




Adjustment Value for the Z-axis Origin

You determine the adjustment value from the discrepancy between the expected and actual values for the thickness of the finished result of two-surface cutting. The estimated adjustment value is one-half the discrepancy. However, be careful to note the sign of the value (plus or minus). When the actual value is larger than the expected value, the adjustment value is negative.

As an example, if data for a height of 50 millimeters yields cutting results that are 50.1 millimeters, the estimated adjustment value is -0.05 millimeters.

The figure below is an example using the swivel clamp.



4-8 Blower Fan

Using the Blower Fan

MARNING Never inadvertently touch the computer or handy panel while performing this

task.


Unintended operation of the machine may result in injury.

CAUTION Caution: cutting tool.

The cutting tool is sharp. To avoid injury, exercise caution.

You use the blower fan with it installed on the tool as shown in the figure. Using the blower fan lets you disperse cutting waste while carrying out cutting. This is not necessarily able to disperse all cutting waste from the workpiece, but can be helpful when you want to keep an eye on the workpiece during cutting, or when you're performing rough cutting or other such operations that produce large amounts of cutting waste. Note, however, that the cutting results do not vary depending on whether you use the blower fan.

Also, when you're using the blower fan, we recommend keeping the spindle speed at 20,000 rpm or lower. Use at higher speeds may cause the cutting waste to be dispersed over a wider area or to fly out from between the front covers or other areas.



Chapter 5 Appendix

5-1 Maintenance

Care and Maintenance of the Cutting Machine

MARNING Never use a pneumatic blower.

This machine is not compatible with a pneumatic blower. Cutting waste may get

inside the machine and cause fire or electrical shock.

MARNING Never use a solvent such as gasoline, alcohol, or thinner to perform cleaning.

Doing so may cause fire.

MARNING Disconnect the power cord before performing cleaning or maintenance.

Attempting such operations while the machine is connected to a power source may

result in injury or electrical shock.

MARNING When using a vacuum cleaner to take up cutting waste, exercise caution to prevent

fire or dust explosion.

Taking up fine cuttings using an ordinary vacuum cleaner may cause danger of fire or explosion. Check with the manufacturer of the vacuum cleaner. When the safety of use cannot be determined, clean using a brush or the like, without using

the vacuum cleaner.

CAUTION Caution: high temperatures.

The cutting tool and spindle motor become hot. Exercise caution to avoid fire or

burns.

CAUTION When performing maintenance, be sure to keep the tool detached.

Contact with the blade may cause injury.

O This machine is a precision device. Carry out daily care and maintenance.

- O Carefully clean away cutting waste. Operating the machine with a large amount of cutting waste present may cause malfunction.
- O Never apply silicone substances (oil, grease, spray, etc.) to the machine. Doing so may cause poor switch contact.
- \bigcirc Never apply lubrication.

Cleaning around the table

After operation, use a brush or the like to clean away any buildup of cutting waste around the table or on the machine.

Cleaning the dust tray

After operation, dispose of any cutting waste that has collected in the dust tray.



Care of the Detection Pin

Carry out daily care for the detection pin. The presence of rust or grime on the detection pin makes accurate detection impossible, which in turn may make it impossible to perform cutting as intended, and may even damage the machine.

Care, Maintenance, and Storage Methods


- O After use, wipe clean using a clean cloth, apply rust-preventive oil generously, and store.
- O When the item will be out of use for a prolonged period, store in a location with low humidity and little fluctuation in temperature.

Maintenance of the Spindle Unit

The spindle unit and the belt are parts that wear out. The replacement cycle varies according to usage conditions, but as a general guide, you should replace them after every 2,000 hours of use. You can use VPanel to view the total working time of the spindle. Refer to this to determine when replacement is needed.

For information on how to replace the spindle unit, refer to the documentation included with the ZS-30 replacement spindle unit.

Checking the total working time of the spindle using VPanel



5-2 What to Do If...

Initialization is not performed or initialization fails.

Is a front cover open?

When starting the machine, close the upper and lower front covers. For safety, initialization is not performed when a cover remains open at startup.

Is anything caught on the spindle head or table?

Check whether something has become caught and is impeding initialization.

VPanel doesn't start correctly.

Has initialization been completed?

Before you start VPanel, first switch on the power to the machine.

P. 42, "Starting and Quitting"

Is the computer connected?

Check whether the connector cable has come loose.

Is the driver installed correctly?

If the connection to the computer is not made in the sequence described, the driver may fail to be installed correctly. VPanel does not function normally when driver is misconfigured. Check again to ensure that the connection was made using the correct procedure.

P. 38, "Installing the Windows-based Driver"

Are two or more machines connected to a single computer?

VPanel cannot control more than one machine at the same time. Never connect two or more instances of this machine to a single computer.

Operations are ignored.

Is the cable connected?

Connect the cable securely. P. 35, "Cable Connections"

Was the machine started according to the correct procedure?

Simply switching on the power does not enable operation. Start the machine using the correct procedure.

P. 42, "Starting and Quitting"

Is a front cover open?

This machine restricts some operations when a front cover is open. Close both the upper and lower front covers.

Is the ERROR light flashing?

The ERROR light is flashing rapidly.

An emergency stop occurred because a serious error was detected. Resuming operation is not possible. A description of the error is displayed in VPanel. Switch off the main power to quit the operation, eliminate the cause, then redo the operation from the beginning. If the emergency stops continue even after eliminating the cause, contact your authorized Roland DG Corp. dealer or Roland DG Corp.

P. 42, "Starting and Quitting," p. 103, "Responding to an Error Message"

The ERROR light is flashing slowly.

Operation was paused because an error was detected. A description of the error is displayed in VPanel. Follow the displayed instructions to resume operation.

P. 51, "Pausing and Resuming Operation"

Is operation paused?

When the PAUSE light is on, it means that operation is paused. When the machine is paused, cutting stops and some operations are restricted. Cancel the paused state.

P. 51, "Pausing and Resuming Operation"

Is a large amount of cutting waste present?

Clean away any cutting waste. Clean the area around the spindle especially carefully.

P. 98, "Care and Maintenance of the Cutting Machine"

Is the handy panel connected correctly?

When inserting, orient correctly and insert fully. Also, before inserting or removing the connector cable for the handy panel, switch off the power to the machine. Making the connection while the power is on may cause the machine to malfunction. P. 35, "Connecting the Handy Panel," p. 42, "Starting and

Quitting"

Is the driver installed correctly?

If the connection to the computer is not made in the sequence described, the driver may fail to be installed correctly. VPanel does not function normally when driver is misconfigured. Check again to ensure that the connection was made using the correct procedure.

P. 38, "Installing the Windows-based Driver"

Are two or more machines connected to a single computer?

VPanel cannot control more than one machine at the same time. Never connect two or more instances of this machine to a single computer.

Is VPanel displaying an error message?

P. 103, "Responding to an Error Message"

The spindle doesn't rotate.

Is a front cover open?

For safety, the spindle does not rotate when a front cover is open.

Close both the upper and lower front covers.

Is a large amount of cutting waste present?

Clean away any cutting waste. Clean the area around the spindle especially carefully.

P. 98, "Care and Maintenance of the Cutting Machine"

Has a setting been made to keep the spindle from rotating?

In VPanel, click the [Setup], then click the [Modeling Machine] tab. Here, select the [Control spindle via commands] check box.

Abnormal cutting is performed.

Have the origin been set at correct location?

If jig attachment, jig-location detection, or detection of the reference position for cutting is not carried out correctly, the origin point may not be set at the correct location. If the origin point is not set at the correct location, cutting at an unintended location or at the wrong depth may occur.

Jig detection failed.

Is the jig, detection pin, or sensor dirty?

Clean away any grime on the jig, detection pin, or sensor. Soiling due to buildup of cutting waste or the like on any of these may impede correct sensor operation, making correct detection of the jig impossible.

The feed rate or spindle speed is wrong.

Has an override been set?

An override changes the feed rate or spindle speed. Check the settings for overrides. Unless you have a special reason for changing them, leave all overrides set at 100%.

The cutting results are not attractive.

Is the workpiece securely mounted in place?

Redo loading of the workpiece. Fasten in place securely, so that the workpiece will not slip out of place or come loose because of tool pressure or vibration during cutting.

→ P. 65, "Square Clamp: Two-surface Cutting," p. 68, "Square Clamp: Circumferential Cutting," p. 78, "Swivel Clamp: Cutting While on the Rotary Axis," p. 81, "Swivel Clamp: Cutting While on the Table," p. 90, "Tube Clamp: Cutting"

Is the tool firmly secured in place?

Retighten the collet to secure in place firmly.

P. 57, "Installing a Tool"

Is the tool tip worn?

If the tip of the tool is worn, replace with a new tool.

Installation is impossible

If installation quits partway through, or if the wizard does not appear when you make the connection with a USB cable, take action as follows.

Windows Vista

- 1. If the [Found New Hardware] appears, click [Cancel] to close it.
- 2. Click the [Start] menu, then right-click [Computer]. Click [Properties].
- 3. Click [Device Manager]. The [User Account Control] appears, click [Continue]. The [Device Manager] appears.
- 4. At the [View] menu, click [Show hidden devices].
- 5. In the list, find [Printers] or [Other device], then double-click it. When the model name you are using or [Unknown device] appears below the item you selected, click it to choose it.
- 6. Go to the [Action] menu, and click [Uninstall].
- 7. In "Confirm Device Uninstall" window, select [Delete the driver software for this device.], then click [OK].
- 8. Detach the USB cable connected to the printer, and the restart Windows.
- 9. Uninstall the driver. Carry out the steps from step 3 in page 102 "Uninstalling the Driver Windows Vista" to uninstall the driver.
- 10. Install the driver again according to the procedure in page 37 "Installing and Setting Up the Software."

Windows 2000/XP

1. If the [Found New Hardware Wizard] appears, click [Finish] to close it.

2.

Windows XP

Click the [Start] menu, then right-click [My Computer]. Click [Properties].

Windows 2000

Right-click [My Computer] on the desktop. Click [Properties].

- 3. Click the [Hardware] tab, then click [Device Manager]. The [Device Manager] appears.
- 4. At the [View] menu, click [Show hidden devices].
- 5. In the list, find [Printers] or [Other device], then double-click
- it. When the model name you are using or [Unknown device] appears below the item you selected, click it to choose it.
- 6. Go to the [Action] menu, and click [Uninstall].
- 7. In "Confirm Device Uninstall" window, crick [OK].
- 8. Close the [Device Manager] and click [OK].
- 9. Detach the USB cable connected to the printer, and the restart Windows.
- 10. Uninstall the driver. Carry out the steps from step 3 in page 102 "Uninstalling the Driver Windows 2000/XP" to uninstall the

driver.

11. Install the driver again according to the procedure in page 37 "Installing and Setting Up the Software."

Uninstalling the Driver

When uninstalling the driver, perform following operation.

Windows Vista

- 1. Before you start uninstallation of the driver, unplug the USB cables from your computer.
- 2. Log on to Windows as "Administrators" right.
- 3. From the [Start] menu, click [Control Panel]. From the [Hardware and Sound] group, click [Printer]. [Printer] folder opens.
- 4. Click the model name's icon you are using. From the [Organize] menu, click [Delete]. The [User Account Control] appears, click [Continue].
- 5. A message prompting you to confirm deletion appears. Click [Yes].
- 6. In the [Printers] folder, right-click any location where no printer icon is present. From the [Run as administrator] menu, select [Server Properties]. The [User Account Control] appears, click [Continue].
- 7. Click the [Drivers] tab, then from the [Installed printer drivers] list, choose the machine to delete. Click [Remove].
- 8. The [Remove Driver And Package] appears, select [Remove driver and driver package]. Click [OK].
- 9. When the prompt message appears, click [Yes].
- 10. The package and driver to delete are displayed. Make sure that what is displayed is the machine you want to delete, then click [Delete].
- 11. The items that have been deleted are displayed. Click [OK].
- 12. Click [Close] on [Remove Driver And Package] window.
- 13. From the [Start] menu, choose [All Programs], then [Accessories], then [Run], and then click [Browse].
- 14. Choose the name of the drive or folder where the driver is located. (*)
- 15. Select "SETUP.EXE" and click [Open], then click [OK].
- 16. The [User Account Control] appears, click [Allow].
- 17. The Setup program for the driver starts.
- 18. Click [Uninstall] to choose it. Select the machine to delete, then click [Start].
- 19. If it is necessary to restart your computer, a window prompting you to restart it appears. Click [Yes].
- 20. The uninstallation finishes after the computer restarts.
- (*) When using the CD-ROM, specify the folder as shown below (assuming your CD-ROM drive is the D drive).

D:\Drivers\25D\WINVISTA

If you're not using the CD-ROM, go to the Roland DG Corp. website (http://www.rolanddg.com/) and download the driver for the machine you want to delete, then specify the folder where you want to expand the downloaded file.

Windows 2000/XP

1. Before you start uninstallation of the driver, unplug the USB

cables from your computer.

2. Log on to Windows as "Administrators" right.

3

Windows XP

From the [Start] menu, click [Control Panel]. Click [Printers and Other Hardware], then click [Printers and Faxes].

Windows 2000

From the [Start] menu, click [Setting]. Then click [Printers].

- 4. Click the model name's icon you are using. From the [File] menu, choose [Delete].
- 5. A message prompting you to confirm deletion appears. Click [Yes].
- 6. Go to [File] and select [Server Properties].
- 7. Click the [Driver] tab, then from the [Installed printer drivers] list, choose the machine to delete.
- 8. Click [Delete]. When the prompt message appears, click [Yes].
- 9. From the [Start] menu, select [Run], then click [Browse].
- 10. From the [File Locations] list, choose the name of the drive or folder where the driver is located. (*)
- 11. Select "SETUP.EXE" and click [Open], then click [OK].
- 12. The Setup program for the driver starts.
- 13. Click [Uninstall] to choose it. Select the machine to delete, then click [Start].
- 14. If it is necessary to restart your computer, a window prompting you to restart it appears. Click [Yes].
- 15. The uninstallation finishes after the computer restarts.
- (*) When using the CD-ROM, specify the folder as shown below (assuming your CD-ROM drive is the D drive).

D:\Drivers\25D\WIN2KXP

If you're not using the CD-ROM, go to the Roland DG Corp. website (http://www.rolanddg.com/) and download the driver for the machine you want to delete, then specify the folder where you want to expand the downloaded file.


5-3 Responding to an Error Message

This section describes the error messages that may appear on the monitor of the computer you're using, and how to take action to remedy the problem. If the action described here does not correct the problem, or if an error message not described here appears, contact your authorized Roland DG Corp. dealer.



Click [Quit]. The machine may have accidentally been switched off, or the connector cable may have come loose. After checking, restart the machine.

P. 42, "Starting and Quitting"



Click [Quit], then restart the machine and redo the operation from the beginning.

P. 42, "Starting and Quitting"



During jig detection, either the detection pin was not installed or the amount of extension was incorrect, and so detection was aborted. The detection operation is canceled. Make sure the detection pin is installed correctly, then redo detection of the jig location.

P. 57, "Installing a Tool"



This appears if "Move to center of rotation Y" is selected in VPanel when jig detection has never been performed. Performing jig detection makes it possible to execute movement to center of rotation Y.

P. 49, "Moving to a Specific Position



The sensor failed to respond during jig detection, and so detection failed. The detection operation is canceled. The sensor may fail to respond if the sensor, detection pin, or jig is dirty. Clean away any grime and redo detection of the jig location.



This is displayed if the handy panel comes loose or malfunctions during operation. Clicking [OK] clears the message. Operations that do not use the handy panel can be continued. If this message continues to appear even after you have switched off the main power, reconnected the handy panel, and redone the operation from the beginning, then the handy panel may be malfunctioning. In such cases, contact your authorized Roland DG Corp. dealer or Roland DG Corp.

P. 35, "Connecting the Handy Panel," p. 42, "Starting and Quitting"



This machine restricts some operations to ensure safety when a front cover is open. Close both the upper and lower front covers.



Operation was paused because a command error occurred. Click [Quit] to quit cutting. Cutting can be resumed by clicking [Continue], but doing so is very likely to result in unintended operation and is not recommended.



An emergency stop occurred because a front cover was opened while cutting was in progress or because the machine experienced load that exceeded its capacity. Operation cannot be resumed. Messages displayed in similar windows, as well as the causes of the emergency stop and the action to take, are described below.

P. 42, "Starting and Quitting"

Cover open error.

A front cover was opened during cutting or spindle rotation. Follow the on-screen messages to switch off the power, close the front cover, and redo the operation from the beginning.

The spindle experienced an excessive load.
The spindle experienced an excessive current.
The spindle motor is running hot.
The spindle control circuit is running hot.

A spindle-motor error occurred. This is caused by prolonged high load on the motor or by excessive torque being applied momentarily. Follow the on-screen messages to switch off the power. The cutting may have exceeded the capacity of the machine. Before restarting, revise the cutting conditions. Also, allow the machine to rest for some time, because the motor may have overheated. If messages like these persist, contact your authorized Roland DG Corp. dealer or Roland DG Corp.

The connector for the rotary axis is detached.

The connector for the rotary axis has come loose or the cable has been damaged, making connection impossible. Follow the on-screen messages to switch off the power. Before restarting, check and correct the status of the connector. If this message persists even though the connector is properly connected, switch off the power and contact your authorized Roland DG Corp. dealer or Roland DG Corp.

The handy panel is incapable of control.

An emergency stop occurred because control using the handy panel became impossible while operation was in progress. Follow the on-screen messages to switch off the power and reconnect the handy panel. If this message persists even though the handy panel is properly connected, the handy panel may be malfunctioning. Switch off the power and contact your authorized Roland DG Corp. dealer or Roland DG Corp.

P. 35, "Connecting the Handy Panel"



An emergency stop occurred because of a failure in initialization or the like. Operation cannot be resumed. Messages displayed in similar windows, as well as the causes of the emergency stop and the action to take, are described below.

*-Limit switch not found.

An emergency stop occurred because initialization failed. Switch the power off, remove any cutting waste or other obstructions impeding operation of the spindle head, then redo the operation from the start. If the message persists even after redoing the operation from the beginning, contact your authorized Roland DG Corp. dealer.

* "X," "Y," "Z," or "A"

Spindle rotation is impossible because the spindle shaft is locked or voltage is too low.

An emergency stop occurred because the spindle cannot be rotated. Possible causes include the spindle shaft being frozen by accumulated cutting waste or the like, or a drop in voltage due to excess load on the spindle. Switch off the power, make sure no obstruction is impeding the operation of the spindle head, and take steps such as revising the cutting conditions as needed. The motor may also have overheated, so allow the machine to rest for some time before restarting. If messages like these still continue to appear, switch off the power and contact your authorized Roland DG Corp. dealer or Roland DG Corp.

The NVRAM could not be accessed.

An emergency stop occurred because the machine's memory unit became partially inaccessible. Follow the on-screen messages to switch off the power and redo the operation from the beginning. If this message persists, switch off the power and contact your authorized Roland DG Corp. dealer or Roland DG Corp.

A broken connection or other damage occurred between the spindle control circuit and the motor. A communication error occurred in the spindle control firmware.

The spindle control firmware is inoperative.

An emergency stop occurred because of a error in spindle control. Follow the on-screen messages to switch off the power and redo the operation from the beginning. If this message persists, switch off the power and contact your authorized Roland DG Corp. dealer or Roland DG Corp.

5-4 Power Rating and Serial Number Locations


Serial Number

This is required when you seek maintenance, servicing, or support. Never peel off the label or let it get dirty.

Power Rating

Use an electrical outlet that meets the requirements for voltage and frequency given here.

Provide a power supply whose amperage is 2.8 A or higher (for 100 to 120 V) or 1.2 A or higher (for 220 to 240 V).



5-5 Expansion Connector Specification

Expansion Connector A

O Pin Connection

Pin Number	Signal	Content	Pin number	Signal	Content
1	PW		13	PG	
2	PW		14	PG	
3	IN8 (Input port 8)	Reserved	15	OUT8(Output port 8)	Reserved
4	IN7 (Input port 7)	Reserved	16	OUT7(Output port 7)	Reserved
5	IN6 (Input port 6)	Reserved	17	OUT6(Output port 6)	Reserved
6	IN5 (Input port 5)	Reserved	18	OUT5(Output port 5)	Reserved
7	IN4 (Input port 4)	Reserved	19	OUT4(Output port 4)	Reserved
8	IN3 (Input port 3)	Reserved	20	OUT3(Output port 3)	Reserved
9	IN2 (Input port 2)	Reserved	21	OUT2(Output port 2)	Reserved
10	IN1 (Input port 1)	Reserved	22	OUT1(Output port 1)	Reserved
11			23	PG	
12			24	PG	

Pin connection




Ribbon connector 24 pins Manufacturer: OMRON Model number: XM882422-11

○ Input Port Specification

Number of input ports: 8 Input voltage: DC 24 V Input current: 7 mA or less

Insulation method: Photo-coupler insulation

Adaptive connection: Output of an external device (sync output)





Notice

The input ports are designed for connecting to non-contact output such as transistor. When connecting a mechanical contact (switch, relay, etc.), be sure to use a minimal-current product. Leakage current of a non-contact circuit (OFF) connected to each input port must be 1 mA or less.

Output Port Specification


Number of output ports: 8 (sync output)

Rated load voltage: DC 24 V

Maximum load current: 8 mA per port (64 mA or less in total)

Leakage current: 0.1 mA or less

Insulation method: Photo-coupler insulation Adaptive connection: Input of an external device






Never apply the load more than stated


The output ports are designed for connecting to the load such as transistor. When connecting the inductive load (relay, etc.), be sure to apply a protection diode for absorbing back EMF to the coil. Inappropriate connection may cause damage to the circuit.

O Example of a Connection to an External Device



107


Expansion Connector B



^{*} We are not responsible for devices connected to this connector.


5-6 Dimensional Drawings

Dimension of Outline




Size of Each Jig


Square Clamp (Large)




Square Clamp (Small)




Swivel Clamp




Tube Clamp



Rotary Axis




Tool Sensor




X-, Y- and Z-axis Travel/ Table Dimension


X- and Y-axis travel/ table dimension



Z-axis travel



Dimensional Drawings for Creating Milling Support Structure



Milling support structure is required for circumferential cutting using the square clamp.

P. 61, "About the Milling Support Structure for Circumferential Cutting"

X-, Y-, and Z-axis origin setting in 3D CAD program other than JewelStudio (circumferential cutting) If you're using a 3D CAD program other than JewelStudio, set X-, Y-, and Z-axis origin at the position described below. This makes the X-, Y-, and Z-axis origin in the cutting data correspond to that set with this machine.

- O X-axis origin: The contact side of the milling support structure and the square clamp.
- \bigcirc Y-, Z-axis origin: The center of the milling support structure.

5-7 Specifications

Main Specifications

	JWX-30				
Cuttable material	Modeling wax				
Loadable workpiece weight	1.9 kg (including the weight of jig)				
Maximum angle of rotation	±18×10 ⁵ ° (±5000 rotations)				
X, Y, and Z operation strokes	X, Y, and Z: 305 x 205 x 100 mm (12 x 8.1 x 3.9 in.)				
X-, Y-, and Z-axis drive system	Stepping motor				
Operating speed	X and Y axes: 0.1 to 60 mm/sec. (0.004 to 2.4 in./sec.)				
	Z axis: 0.1to 30 mm/sec. (0.004 to 1.2 in./sec.)				
	A axis: 11.25rpm				
Software resolution	X, Y and Z axis: 0.01mm/step (0.0004 in./step), A axis: 0.0225°/step				
Mechanical resolution	X and Y axis: 0.00125 mm/step (0.00005in./step) (micro-step control)				
	Z axis: 0.00125 mm/step (0.00005in./step) (micro-step control)				
	A axis: 0.0028125° /step (micro-step control)				
Spindle motor	Brushless DC motor, maximum 100W				
Spindle speed	6,000 to 30,000 rpm				
Tool chuck	Collet method, maximum tool shank diameter: 6.35 mm (0.25 in.)				
Interface	USB (compliant with Universal Serial Bus Specification Revision 1.1)				
Control command set	RML-1				
Required power-supply amperage	Voltage and frequency: AC 100 to 120 V/220 to 240 V \pm 10%, 50/60 Hz (overvoltage category II, IEC 60664-1) Required power capacity: 2.8 A (100 to 120 V)/ 1.2 A (220 to 240 V)				
Power consumption	275 W				
Operating noise	During operation: 60 dB (A) or less (when not cutting), during standby: 40 dB (A) or less				
External dimensions	Width x depth x height: 606 x 656 x 557 mm (23.9 x 25.9 x 22 in.)				
Weight	47 kg (104 lb)				
Installation Environment	Operating environment: Temperature of 5 to 40°C (41 to 104°F), 35 to 80% relative humidity (no condensation) Ambient pollution degree: 3 (as specified by IEC 60664-1)				
Included items	Power cord, handy panel, tools for modeling (ball end mill, diameter 3.175mm / conical end mill, diameter 3.175 mm), collet (diameter 3.175 mm), detection pin, hexagonal screwdriver, hexagonal wrench, cap screws (10), spanner (10 mm, 17mm), modeling wax (three kinds), clamp holder, square clamp (large), square clamp (small), swivel clamp, tube clamp, dust tray, blower fan, USB cable, User's Manual (this document), SRP Player Installation and Setup Guide, SRP Player CD-ROM, Roland Software Package CD-ROM, Roland JewelStudio DVD-ROM				

System Requirements for USB Connection

Computer	Model preinstalled with Windows 7, Vista, XP, 2000 or upgraded computer originally preinstalled with Windows 2000 or later	
USB cable	Use the included USB cable.	

产品中有毒有害物质或元素的名称及含量

	有毒有害物质或元素						
部件名称	铅(Pb)	汞(Hg)	镉(Cd)	六价铬 (Cr(VI))	多溴联苯 (PBB)	多溴二苯醚 (PBDE)	
印刷电路板	×	0	×	0	0	0	
头部	×	0	0	0	0	0	
壳体、底架	×	0	0	0	0	0	
电源	×	0	×	0	0	0	
其他(电缆、附件等)	×	0	0	0	0	0	

- 〇:表示该有毒有害物质在该部件所有均质材料中的含量均在 GB/T26572-2011 标准规定的限量要求以下。
- ×:表示该有毒有害物质至少在该部件的某一均质材料中的含量超出 GB/T26572-2011 标准规定的限量要求。

环保使用期限



此标志适用于在中国国内销售的电子信息产品,表示环保使用期限的年数。 所谓环保使用期限是指在自制造日起的规定期限内,产品中所含的有害物质 不致引起环境污染,不会对人身、财产造成严重的不良影响。

环保使用期限仅在遵照产品使用说明书,正确使用产品的条件下才有效。 不当的使用,将会导致有害物质泄漏的危险。

For EU Countries -



This product must be disposed of separately at your local waste recycling center. Do not dispose of in household waste bin.



Lever dit product in bij een lokaal afvalverzamelpunt. NIET met normaal huishoudelijk afval afvoeren.



Bitte führen Sie dieses Produkt separat Ihrer örtlichen Entsorgungsstelle zu. Bitte nicht mit dem normalen Hausmüll entsorgen.



Dette Produkt skal smides særskilt væk på den lokale affalds- og genbrugsstation. Må ikke smides ud sammen med almindeligt husholdningsaffald.



Ne jetez pas le produit avec vos ordures ménagères. Portez-le dans un centre recyclage des déchets.



Tätä tuotetta ei saa hävittää normaalien talousjätteiden mukana, vaan se on toimitettava ongelmajätteiden keräilypisteeseen hävitettäväksi.



Questo prodotto deve essere smaltito negli appositi contenitori per la raccolta differenziata, non buttare nel cestino dei rifiuti casalinghi.



Produkten måste kasseras separat på din lokala återvinningscentral. Släng inte produkten tillsammans med hushållssoporna.



Este producto debe devolverse al centro de reciclaje más cercano a su domicilio para su correcta eliminación. No lo tire a la basura.



Μην πετάξετε το αντικείμενο αυτό στο καλάθι των απορριμμάτων. Αφαιρέστε τις μπαταρίες και προσκομίστε το στο τοπικό κέντρο ανακύκλωσης.



Deite fora separadamente este produto no seu centro de reciclagem local. Não o deite fora no seu caixote do lixo.

Roland

